

# Aircraft Tooling, Inc. Capabilities List

Aircraft Tooling, Inc.  
FAA Repair Station No. RM1R457K  
EASA 145.4109  
Aircraft Tooling, Inc. Capabilities List

**Aircraft Tooling Inc.**  
11250 Luna Road  
Dallas, Texas 75229  
Main: (972) 869-1988  
Facsimile: (972) 869-1651  
Website: [www.atirepairstation.com](http://www.atirepairstation.com)

**Rex W. Johnson (QC Manager)**  
Direct: (972) 869-0334  
Facsimile: (972) 869-0334  
Email: [rexj@atirepairstation.com](mailto:rexj@atirepairstation.com)

**Oscar Escobedo (FAA PMI)**  
FAA Flight Standards District Office  
1431 Greenway Drive, Suite 1000  
Irving, TX 75038  
Direct: (972) 582-1826  
Main: (972) 852-1800  
Facsimile: (972) 582-1872  
Email: [oscar.x.escobedo@faa.gov](mailto:oscar.x.escobedo@faa.gov)

Capabilities List

Aircraft Tooling, Inc.  
Capabilities List

Revision: 35  
Revised 01/27/12

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
200811316	Nlg Outer Cylinder	Repair - SS	32-20-03/FAA-DER	Dowty	C-601	LG	1/27/2012	RWJ	Yes
201522255	Bearing	Repair - SS	P.O. Intructions	Airbus	A320	LG		RWJ	Yes
697039301	Rear Hub Half	Repair	61-10-43	Dowty	C-130	Prop.		RWJ	Yes
697039314	Prop Hub	Repair	61-10-43	Dowty	C-130	Prop.		RWJ	Yes
697070241	Prop Hub	Repair	31-10-49	Dowty	C-130	Prop.		RWJ	Yes
113A2672-1	Track (Titanium)	Repair	57-53-05	Boeing	737	AF		RWJ	Yes
113A2672-3	Track (Titanium)	Repair	57-53-05	Boeing	737	AF		RWJ	Yes
113A8700-1	Center Door Rod Assy.	Repair	32-13-23	Boeing	737	LG		RWJ	Yes
115A1500-13	Beam Support Link	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
115A1500-14	Beam Support Link	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
115A1610-1	Pin	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
115A5005-1	Fwd Trunnion Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
115A5240-1	Housing Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
115A5260-1	Trunnion Support Pin	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
115A5280-1	Fuse Pin Retention Cap	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
115A5281-1	Lube Extension	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
115A5283-1	Nut	Repair	57-15-01	Boeing	737	AF		RWJ	Yes
115A5284-1	Rod	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A0101-1	Ring Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1127-1	Brake Sleeve	Overhaul	32-11-12	Boeing	737	LG		RWJ	Yes
161A1140-1	Upper Torsion Link (Titanium)	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
161A1142-1	Torsion Link (Titanium Part)	Overhaul	32-11-12	Boeing	737	LG		RWJ	Yes
161A1146-1	Pin	Overhaul	32-11-12	Boeing	737	LG		RWJ	Yes
161A1154-1	Gland Nut	Overhaul	32-11-12	Boeing	737	LG		RWJ	Yes
161A1167-4	Carrier (Titanium Part)	Repair	32-11-12	Boeing	737	LG		RWJ	Yes
161A1168-1	Bearing Carrier	Repair	32-11-12	Boeing	737	LG		RWJ	Yes
161A1185-1	Fwd Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1185-3	Fwd Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1185-5	Fwd Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1185-7	Fwd Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1185-9	Fwd Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1187-1	Race	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1188-1	Trunnion Pin Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1188-10	Trunnion Pin Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1188-2	Trunnion Pin	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes

Capabilities List

Aircraft Tooling, Inc.  
Capabilities List

Revision: 35  
Revised 01/27/12

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
161A1188-3	Trunnion Pin Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1188-4	Trunnion Pin	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1188-5	Trunnion Pin Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1188-6	Trunnion Pin	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1188-7	Trunnion Pin Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1188-8	Trunnion Pin	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1194-1	Retaining Ring	Overhaul	32-11-09	Boeing	737	LG		RWJ	Yes
161A1203-1	Nut-Retainer	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1214-3	Apex Pin	Overhaul	32-11-12	Boeing	737	LG		RWJ	Yes
161A1500-1	Aft Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1500-2	Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1500-2	Aft Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1500-3	Aft Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1500-4	Aft Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1501-1	Outer Race (Titanium)	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1501-2	Outer Race (Titanium)	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1502-1	Split Ball Assy.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1503-1	Lock Plate	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1503-2	Lock Plate	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1504-1	Retaining Nut	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A1505-1	Locking Tab	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
161A2331-1	Pin	Overhaul	32-11-09	Boeing	737	LG		RWJ	Yes
161A4300-2	Hanger Link (Titanium Part)	Repair	32-11-13	Boeing	737	LG		RWJ	Yes
161A7000-3	Actuator Pin	Overhaul	32-32-27	Boeing	737	LG		RWJ	Yes
161A7118-1	Pin	Overhaul	32-32-27	Boeing	737	LG		RWJ	Yes
161A7118-2	Pin	Overhaul	32-32-27	Boeing	737	LG		RWJ	Yes
161N1258	Metering Pin	Overhaul	32-11-95	Boeing	757	LG		RWJ	Yes
161N1621-1	Tow Fitting	Overhaul	32-11-56	Boeing	757	LG		RWJ	Yes
161N1621-2	Tow Fitting	Overhaul	32-11-56	Boeing	757	LG		RWJ	Yes
161N1805-1	Pivot Pin	Overhaul	32-11-32	Boeing	757	LG		RWJ	Yes
161N1823-1	Pin	Overhaul	32-11-32	Boeing	757	LG	8/4/2011	RWJ	Yes
161N1833-2	Bushing	Repair	32-11-56	Boeing	757	LG		RWJ	Yes
161T1133-3	Tow Fitting	Overhaul	32-11-50	Boeing	767	LG		RWJ	Yes
161T1156-4	Metering Pin	Repair	32-11-40	Boeing	737	LG	01/24/12	RWJ	Yes
161T1190-1	Aft Race Assy.	Overhaul	32-11-81	Boeing	767	LG		RWJ	Yes

Capabilities List

Aircraft Tooling, Inc.  
Capabilities List

Revision: 35  
Revised 01/27/12

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
161T2106-2	Spindle	Overhaul	32-11-81	Boeing	767	LG		RWJ	Yes
161T2106-2-3	Spindle	Overhaul	32-11-81	Boeing	767	LG		RWJ	Yes
161T2106-3	Spindle	Overhaul	32-11-81	Boeing	767	LG		RWJ	Yes
161T2108-1	Lower Spindle	Overhaul	32-11-36	Boeing	767	LG		RWJ	Yes
161T2108-2	Lower Spindle	Overhaul	32-11-36	Boeing	767	LG		RWJ	Yes
161T2875-1	Bushing	Repair	32-11-36	Boeing	767	LG		RWJ	Yes
161T2875-3	Bushing	Repair	32-11-36	Boeing	767	LG		RWJ	Yes
161T2877-2	Bushing	Repair	32-11-36	Boeing	767	LG		RWJ	Yes
161T5010-1	Pin	Repair	32-11-36	Boeing	767	LG		RWJ	Yes
161T6105-2	Lower Spindle	Overhaul	32-11-36	Boeing	767	LG		RWJ	Yes
161T6107-2	Spindle	Overhaul	32-11-36	Boeing	767	LG		RWJ	Yes
161T7125-1	Torsion Pin	Overhaul	32-11-36	Boeing	767	LG		RWJ	Yes
161T7125-2	Torsion Pin	Overhaul	32-11-36	Boeing	767	LG		RWJ	Yes
161T7133-2	Mlg Axle	Overhaul	32-11-36	Boeing	767	LG		RWJ	Yes
161T7140-1	Brake Rod Pin	Overhaul	32-11-36	Boeing	767	LG		RWJ	Yes
161T7140-2	Brake Rod Pin	Overhaul	32-11-36	Boeing	767	LG		RWJ	Yes
161T7193-1	Pivot Pin	Overhaul	32-11-36	Boeing	767	LG		RWJ	Yes
161W1345-2	Race	Repair	32-11-07	Boeing	777	LG		RWJ	Yes
161W1501-2	Fitting	Overhaul	32-11-82	Boeing	777	LG		RWJ	Yes
162A0301-1	Trunnion Pin	Overhaul	32-21-07	Boeing	737	LG		RWJ	Yes
162A0302-1	Trunnion Pin	Overhaul	32-21-07	Boeing	737	LG		RWJ	Yes
162A1160-1	Tow Fitting Assy.	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1160-5	Tow Fitting	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1191-1	Metering Pin	Repair	32-21-49	Boeing	757	LG		MA	Yes
162A1306-1	Pin	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1310-1	Pin	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1311-1	Upper Torsion Link	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1312-1	Lower Torsion Link	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1313-1	Lower Torsion Link Assy.	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1315-1	Upper Torsion Link Assy.	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1404-3	Steering Collar Assy.	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1404-4	Steering Collar Assy.	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1405-5	Steering Sleeve (Titanium)	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1405-6	Steering Sleeve (Titanium)	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1411-1	Pin	Overhaul	32-21-16	Boeing	737	LG		RWJ	Yes

Capabilities List

Aircraft Tooling, Inc.  
Capabilities List

Revision: 35  
Revised 01/27/12

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
162A1417-4	Steering Plate (Titanium)	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1417-5	Steering Plate (Titanium)	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1417-6	Steering Plate (Titanium)	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1420-1	Steering Collar	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1421-1	Steering Sleeve (Titanium)	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1421-2	Steering Sleeve (Titanium)	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1421-4	Steering Sleeve (Titanium)	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1501-1	Lower Centering Cam	Overhaul	32-21-12	Boeing	737	LG		RWJ	Yes
162A1510-1	Lower Bearing Carrier	Repair	32-21-12	Boeing	737	LG		RWJ	Yes
162A1511-4	Upper Bearing Carrier	Repair	32-21-12	Boeing	737	LG		RWJ	Yes
162A2115-5	Link Assy. Aft	Overhaul	32-21-22	Boeing	737	LG		RWJ	Yes
162A2301-1	Trunnion Pin Assy.	Overhaul	32-21-07	Boeing	737	LG		RWJ	Yes
162A2301-2	Trunnion Pin	Overhaul	32-21-07	Boeing	737	LG		RWJ	Yes
162A2302-1	Pin	Overhaul	32-21-07	Boeing	737	LG		RWJ	Yes
162N1142-*	Upper Support Plate	Repair	32-21-49	Boeing	757	LG		RWJ	Yes
162N1191-1	Metering Pin	Overhaul	32-21-49	Boeing	757	LG	11/23/2011	MA	Yes
162W1400-*	Tube Assy.	Repair	32-21-03	Boeing	777	LG		RWJ	Yes
162W1402-*	Lower Steering Plate	Repair	32-21-03	Boeing	777	LG		RWJ	Yes
162W1402-2	Lower Steering Plate/Tube Assy.	Repair	32-21-03	Boeing	777	LG		RWJ	Yes
173-1034-5	Idler Link Assy.	Repair	78-30-12	Boeing	737	Acc.		RWJ	Yes
251U3319-3	Torque Tube Assy.	Repair	27-21-44	Boeing	747	AF		RWJ	Yes
256T3438-2	Housing	Repair	27-51-37	Boeing	767	AF		RWJ	Yes
256W2243-2	Housing	Repair	27-81-67	Boeing	777	AF		RWJ	Yes
273N2037-2	Barrel	Overhaul	32-32-56	Boeing	757	LG		RWJ	Yes
273N2037-3	Barrel Assy.	Overhaul	32-32-56	Boeing	757	LG		RWJ	Yes
273N2041-1	Rod End Assy.	Overhaul	32-32-56	Boeing	757	LG		RWJ	Yes
273N2041-2	Rod End	Overhaul	32-32-56	Boeing	757	LG		RWJ	Yes
273T0065-2	End Head	Repair	32-34-00	Boeing	767	LG		RWJ	Yes
273T1105-1	Head End	Repair	32-32-00	Boeing	767	LG		RWJ	Yes
273T4117-2	Head End	Repair	32-34-00	Boeing	767	LG		RWJ	Yes
275N1228	Trunnion	Overhaul	32-51-15	Boeing	757	LG		RWJ	Yes
275N1228-1	Trunnion	Overhaul	32-51-15	Boeing	757	LG		RWJ	Yes
275N1228-3	Trunnion	Overhaul	32-51-15	Boeing	757	LG		RWJ	Yes
275T6223	Trunnion	Repair	32-51-10	Boeing	767	LG		RWJ	Yes
275T6223-1	Trunnion	Repair	32-51-10	Boeing	767	LG		RWJ	Yes

Capabilities List

Aircraft Tooling, Inc.  
Capabilities List

Revision: 35  
Revised 01/27/12

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
295W1702-3	Trunnion	Repair	32-51-13	Boeing	777	LG		RWJ	Yes
310A1020-11	Eng. Mount Assy.	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1020-14	Aft Mount Assy.	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1020-20	Thrust Link Assy.	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1020-21	Aft Engine Mount Assy.	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1020-22	Aft Engine Mount	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1020-26	Aft Mount Assy.	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1020-3	Aft Engine Mount Assy.	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1021-1	Mount	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1021-2	Mount	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1022-1	Crossbeam Assy.	Overhaul	54-50-01	Boeing	737	Acc.		RWJ	Yes
310A1022-7	Crossbeam	Overhaul	54-50-01	Boeing	737	Acc.		RWJ	Yes
310A1023-1	Link Assy.	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1023-2	Link Assy.	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1025-1	Fitting	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1026-1	Failsafe Fitting	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1028-1	Hanger	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1028-7	Hanger	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1031-1	Pin	Overhaul	54-50-01	Boeing	737	Acc.		RWJ	Yes
310A1032-3	Link Assy.	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1032-5	Link Assy.	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1033-1	Evener Bar	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1033-3	Evener Bar	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1033-5	Evener Bar	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1035-1	Shear Pin	Repair	54-50-01	Boeing	737	Acc.		RWJ	Yes
310A1036-1	Thrust Link Mount	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1036-12	Shouldered Bolt	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A1036-2	Thrust Link Mount	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1036-5	Thrust Link	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1036-6	Fitting Assy.	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1039-7	Bolt Retainer	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1041-1	Cone Bolt	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1041-2	Cone Bolt	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1041-5	Cone Bolt Assy.	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A1041-7	Cone Bolt	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes

Capabilities List

Aircraft Tooling, Inc.  
Capabilities List

Revision: 35  
Revised 01/27/12

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
310A1043-3	Bolt	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
310A2020-10	Fwd Engine Mount Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2020-11	Forward Mount Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2020-5	Fwd Engine Mount	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2020-6	Shear Bushing	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2021-4	Fitting Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2022-3	Link Assy. Fwd.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2024-2	Shear Pin	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2028-11	Fitting Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2028-13	Fitting Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2029-11	Bolt	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2029-19	Bolt	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2030-11	Aft Engine Mount Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2030-15	Aft Engine Mount Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2030-17	Aft Engine Mount	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2030-6	Aft Engine Mount	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2031-22	Hanger Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2031-23	Hanger Assy.	Repair	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2031-24	Hanger Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2031-9	Hanger Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2033-3	Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2033-5	Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2033-7	Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2033-8	Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2034-13	Center Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2034-14	Link Assy. - Ctr	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2034-3	Link Assy. - Ctr	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2034-4	Link Assy	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2034-7	Center Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2034-8	Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2035-3	Right Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2035-5	Link Assy.-Right	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2035-7	Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2035-8	Link Assy. (R/H)	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2036-5	Evener Bar	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes

Capabilities List

Aircraft Tooling, Inc.  
Capabilities List

Revision: 35  
Revised 01/27/12

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
310A2036-8	Evener Bar	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2037-10	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2037-11	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2037-12	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2037-13	Pin	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2037-14	Pin	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2037-15	Pin	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2037-16	Pin	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2037-4	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2037-5	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2037-6	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2037-7	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2037-8	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2037-9	Pawl Pin	Overhaul	71-21-37	Boeing	737	AF		RWJ	Yes
310A2039-1	End Cap	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2039-2	End Cap	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2039-3	End Cap	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2041-10	Thrust Link Assy.	Overhaul	71-04-26	Boeing	737	Acc.		RWJ	Yes
310A2041-5	Thrust Link Assy.	Overhaul	71-04-26	Boeing	737	Acc.		RWJ	Yes
310A2041-6	Link Assy.	Overhaul	71-04-26	Boeing	737	Acc.		RWJ	Yes
310A2041-9	Thrust Link Assy.	Overhaul	71-04-26	Boeing	737	Acc.		RWJ	Yes
310A2042-2	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2042-3	Pin	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310A2043-1	End Cap	Overhaul	71-21-37	Boeing	737	Acc.		RWJ	Yes
310N3021-2	Fitting	Overhaul	71-21-15	Boeing	757	Acc.		RWJ	Yes
310N3021-5	Fitting	Overhaul	71-21-15	Boeing	757	Acc.		RWJ	Yes
310N3036-2	Shouldered Bolt	Overhaul	71-21-15	Boeing	757	Acc.		RWJ	Yes
310T1036-19	Bolt	Overhaul	71-21-13	Boeing	767	Acc.		RWJ	Yes
310T1036-22	Bolt-Shoulder	Overhaul	71-21-14	Boeing	767	Acc.		RWJ	Yes
310T1036-23	Bolt-Shoulder	Overhaul	71-21-14	Boeing	767	Acc.		RWJ	Yes
310T1036-24	Bolt-Shoulder	Overhaul	71-21-14	Boeing	767	Acc.		RWJ	Yes
310T1036-7	Shouldered Bolt	Overhaul	71-21-13	Boeing	767	Acc.		RWJ	Yes
310T3037-2	Pin-Shear	Overhaul	71-21-14	Boeing	767	Acc.		RWJ	Yes
310T3151-18	Washer-Special	Overhaul	71-21-14	Boeing	767	Acc.		RWJ	Yes
310T3151-19	Washer-Special	Overhaul	71-21-14	Boeing	767	Acc.		RWJ	Yes

Capabilities List

Aircraft Tooling, Inc.  
Capabilities List

Revision: 35  
Revised 01/27/12

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
310T4012-2	Hinge Pin	Overhaul	71-21-16	Boeing	767	Acc.		RWJ	Yes
310T4021-1	Fitting Assy.	Overhaul	71-21-16	Boeing	767	Acc.		RWJ	Yes
310T4021-2	Fitting	Overhaul	71-21-16	Boeing	767	Acc.		RWJ	Yes
310T4021-3	Fitting	Repair	71-21-16	Boeing	747	Acc.		RWJ	Yes
310T4021-4	Fitting	Overhaul	71-21-16	Boeing	747	Acc.		RWJ	Yes
310T4021-5	Fitting	Overhaul	71-21-16	Boeing	767	Acc.		RWJ	Yes
310T4038-1	Shear Pin	Overhaul	71-21-16	Boeing	747	Acc.		RWJ	Yes
310U2020-18	Aft Engine Mount Assy	Overhaul	71-21-14	Boeing	767	Acc.		RWJ	Yes
310U2031-23	Upper Fitting Assy.	Overhaul	71-21-14	Boeing	767	Acc.		RWJ	Yes
310U2032-3	Link Assy.	Overhaul	71-21-14	Boeing	767	Acc.		RWJ	Yes
310U2033-25	Lower Fitting Assy.	Overhaul	71-21-14	Boeing	767	Acc.		RWJ	Yes
310U2033-27	Lower Fitting Assy.	Overhaul	71-21-14	Boeing	767	Acc.		RWJ	Yes
310U2039-1	Retainer-Bolt	Overhaul	71-21-14	Boeing	767	Acc.		RWJ	Yes
310U2039-2	Retainer-Bolt	Overhaul	71-21-14	Boeing	767	Acc.		RWJ	Yes
310U2039-5	Retainer-Bolt	Overhaul	71-21-14	Boeing	767	Acc.		RWJ	Yes
310W3020-4	Fitting	Repair	71-21-21	Boeing	777	Acc.		RWJ	Yes
310W3021-5	Fitting Assy.	Overhaul	71-21-21	Boeing	777	Acc.		RWJ	Yes
310W3023-5	Thrust Link Assy.	Repair	71-21-21	Boeing	777	Acc.		RWJ	Yes
310W3035-5	Pivot Pin	Repair	71-21-21	Boeing	777	Acc.		RWJ	Yes
310W3035-6	Link Pin	Repair	71-21-21	Boeing	777	Acc.		RWJ	Yes
311A1090-1	Pin	Overhaul	54-50-01	Boeing	737	Acc.		RWJ	Yes
311A1090-2	Pin	Overhaul	54-50-01	Boeing	737	Acc.		RWJ	Yes
311A1091-1	Pin	Overhaul	54-50-01	Boeing	737	Acc.		RWJ	Yes
311A1092-2	Fuse Pin	Overhaul	54-50-01	Boeing	737	Acc.		RWJ	Yes
311A1562-*	Cross Beam	Overhaul	54-50-01	Boeing	737	Acc.		RWJ	Yes
311A1710-5	Pylon Link	Overhaul	54-50-01	Boeing	737	Acc.		RWJ	Yes
311A1710-8	Pylon Link	Overhaul	54-50-01	Boeing	737	Acc.		RWJ	Yes
311A1730-1	Brace Assy.	Overhaul	54-50-01	Boeing	737	Acc.		RWJ	Yes
311A1730-5	Brace Assy.	Overhaul	54-50-01	Boeing	737	Acc.		RWJ	Yes
311A1730-7	Brace Assy.	Overhaul	54-50-01	Boeing	737	Acc.		RWJ	Yes
311N3510-181	Ground Clip	Repair - SS		Boeing	757	AF		RWJ	Yes
314A1129-6	Seal	Repair - SS	71-13-26	Boeing	737	AF		RWJ	Yes
314A1129-7	Seal	Repair - SS	71-13-26	Boeing	737	AF		RWJ	Yes
314A1502-38	L/H Support	Overhaul	78-11-23	Boeing	737	Acc.		RWJ	Yes
314A1502-39	Support Assy.	Overhaul	78-11-23	Boeing	737	Acc.		RWJ	Yes

Capabilities List

Aircraft Tooling, Inc.  
Capabilities List

Revision: 35  
Revised 01/27/12

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
314A1502-40	Exhaust Seal	Overhaul	78-11-23	Boeing	737	Acc.		RWJ	Yes
314A1502-41	Exhaust Seal Assy.	Overhaul	78-11-23	Boeing	737	Acc.		RWJ	Yes
314A1502-52	Exhaust Seal	Overhaul	78-11-23	Boeing	737	Acc.		RWJ	Yes
314A1502-53	Exhaust Seal	Overhaul	78-11-23	Boeing	737	Acc.		RWJ	Yes
314A1502-60	Exhaust Seal	Overhaul	78-11-23	Boeing	737	Acc.		RWJ	Yes
314A1502-61	Exhaust Seal	Overhaul	78-11-23	Boeing	737	Acc.		RWJ	Yes
314W1300-8	Fan Cowl Beam Assy.	Repair	71-11-08	Boeing	777	AF		RWJ	Yes
315A1511-1	Link Assy.	Repair	78-31-23	Boeing	737	Acc.		RWJ	Yes
315A1816-2	Piston	Repair	78-31-05	Boeing	737	Acc.		RWJ	Yes
315A1816-3	Piston	Repair	78-31-18	Boeing	737	Acc.		RWJ	Yes
315A1842-2	Piston	Repair	78-31-04	Boeing	737	Acc.		RWJ	Yes
315A1842-4	Piston	Repair	78-31-19	Boeing	737	Acc.		RWJ	Yes
315A2808-1	Cylinder	Repair	78-31-18	Boeing	737	Acc.		RWJ	Yes
332A1908-54	Deflector Assy.	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
335-106-403-0	Spinner Cone	Repair	70-44-10	CFM	737	Acc.		RWJ	Yes
337-005-118-0	Spinner Cone	Repair	70-44-10	CFM	737	Acc.		RWJ	Yes
352A1200-31	Strut Assy.	Repair	49-13-12	Boeing	737	AF		RWJ	Yes
352A1200-32	Strut Assy.	Repair	49-13-12	Boeing	737	AF		RWJ	Yes
47127-3	Pivot Pin	Repair	32-21-04	Bombardier	Q400	LG		RWJ	Yes
5961560-1	Bearing	Repair - SS	32-21-04	MD	MD-80	LG		RWJ	Yes
65-20744-*	Support Tube	Repair	32-22-04	Boeing	727	LG		RWJ	Yes
65-2199-*	Trunnion Assy.	Repair	32-08-01	Boeing	707	LG		RWJ	Yes
65-27147-7	Outer Cylinder	Repair	DAP 104C-4702-13	Boeing	727	LG	10/13/2011	MA	Yes
65-44711-5	Steering Barrel	Overhaul	32-50-11	Boeing	737	LG		RWJ	Yes
65-46102-21	Lower Torsion Link	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46102-23	Lower Torsion Link	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46103-13	Upper Drag Strut	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46106-11	Universal Assy.	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46106-7	Universal Assy.	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46106-8	Universal	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46106-9	Universal	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46107-1	Universal Assy.	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
65-46108-17	Actuator Beam	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes
65-46108-19	Actuator Beam Assy.	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes
65-46108-3	Actuator Beam	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes

Capabilities List

Aircraft Tooling, Inc.  
Capabilities List

Revision: 35  
Revised 01/27/12

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
65-46109-12	Arm	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46109-14	Mlg Actuator Beam Arm	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46109-14L	Arm	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46109-18	Arm	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46109-20	Actuator Beam Arm	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46112-19	Mlg Support Link	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes
65-46112-22	Support Link	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes
65-46112-30	Support Link	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes
65-46113-12	Trunnion Pin	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46113-16	Trunnion Pin	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46113-19	Trunnion Pin	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46113-21	Trunnion Pin	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46113-23	Trunnion Pin	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46113-25	Mlg Trunnion Pin	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46124-1	Metering Pin	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65-46124-3	Metering Pin	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65-46124-5	Metering Pin	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65-46133-5	Up Side Strut Assy.	Overhaul	32-12-11	Boeing	737	LG		RWJ	Yes
65-46135-13	Reaction Link Assy.	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
65-46135-20	Reaction Link Assy.	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
65-46138-10	Downlock Link Assy.	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
65-46138-23	Downlock Link	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
65-46139-14	Link Assy.	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
65-46139-9	Lower Downlock Link	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
65-46140-6	Tee Bolt	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46140-7	Tee Bolt Fitting	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46140-9	Tee Bolt	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-46141-11	(L/H) Uplock Assy.	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
65-46141-12	(R/H) Uplock Assy.	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
65-46141-17	L/H Uplock Assy.	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
65-46141-18	(R/H) Uplock Assy.	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
65-46141-21	Mlg Uplock Assy.	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
65-46141-22	Mlg Uplock Assy.	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65-46142-7	Uplock Hook	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
65-46146-1	Support Shaft	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes

Capabilities List

Aircraft Tooling, Inc.  
Capabilities List

Revision: 35  
Revised 01/27/12

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
65-46146-2	Support Shaft	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes
65-46146-3	Support Shaft	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes
65-46146-4	Support Shaft	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes
65-46147	Axle Sleeve	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65-46156-1	Drain Tube	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65-46156-3	Mlg Drain Tube	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65-46156-5	Drain Tube	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65-46159-7	M.L.G. Support Tube	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65-46159-9	Orifice Tube	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65-46160-10	Support Tube	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65-46160-11	Support Tube	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65-46160-8	Support Tube	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65-46160-9	Orifice Support Tube	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65-46202-9	Upper Torsion Link	Overhaul	32-26-01	Boeing	737	LG		RWJ	Yes
65-46203	Steering Collar	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46203*	Steering Collar	Overhaul	32-21-48 & 32-26-01	Boeing	737	LG		RWJ	Yes
65-46203-20	Steering Collar	Overhaul	32-26-01	Boeing	737	LG		RWJ	Yes
65-46203-20M	Steering Collar	Overhaul	32-26-01	Boeing	737	LG		RWJ	Yes
65-46203-24	Steering Collar	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46203-24M	Steering Collar	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46203-25	Steering Collar Assy.	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46203-26	Steering Collar	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46203-26M	Steering Collar	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46203-27	Steering Collar	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46203-28	Steering Collar	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46203-29	Steering Collar	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46203-29M	Steering Collar	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46203-31	Steering Collar	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46203-31M	Steering Collar	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46210-33	Upper Steering Plate	Overhaul	32-21-58	Boeing	737	LG		RWJ	Yes
65-46210-34	Lower Steering Plate	Overhaul	32-32-27	Boeing	737	LG		RWJ	Yes
65-46211-7	Nlg Outer Cylinder	Overhaul	32-21-11	Boeing	737	LG		RWJ	Yes
65-46211-8	Nlg Outer Cylinder	Overhaul	32-21-16	Boeing	737	LG		RWJ	Yes
65-46215-12	Nlg Inner Cylinder	Overhaul	32-21-11	Boeing	737	LG		RWJ	Yes
65-46215-13	Inner Cylinder	Overhaul	32-21-11	Boeing	737	LG		RWJ	Yes

Capabilities List

Aircraft Tooling, Inc.  
Capabilities List

Revision: 35  
Revised 01/27/12

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
65-46219-1	Metering Pin	Overhaul	32-12-11	Boeing	737	LG		RWJ	Yes
65-46219-2	Metering Pin	Overhaul	32-21-58	Boeing	737	LG		RWJ	Yes
65-46221-11	Gland Nut	Overhaul	32-21-58	Boeing	737	LG		RWJ	Yes
65-46221-12	Gland Nut	Overhaul	32-21-58	Boeing	737	LG		RWJ	Yes
65-46227-1	Upper Centering Cam	Overhaul	32-21-58	Boeing	737	LG		RWJ	Yes
65-46228-3	Lower Centering Cam	Overhaul	32-21-11	Boeing	737	LG		RWJ	Yes
65-46230-1	Lower Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-46230-11	Lower Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-46230-13	Lower Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-46230-15	Lower Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-46230-5	Lower Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-46230-7	Lower Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-46240-11	Brace Assy.	Overhaul	32-34-13	Boeing	737	LG		RWJ	Yes
65-46240-13	Lock Brace Assy.	Overhaul	32-34-13	Boeing	737	LG		RWJ	Yes
65-46240-15	Lock Brace Assy.	Overhaul	32-34-13	Boeing	737	LG		RWJ	Yes
65-46242-11	Lock Link Assy.	Overhaul	32-34-13	Boeing	737	LG		RWJ	Yes
65-46242-13	Lock Link Assy.	Overhaul	32-34-13	Boeing	737	LG		RWJ	Yes
65-46245-11	Nlg Lock Link Assy.	Overhaul	32-34-13	Boeing	737	LG		RWJ	Yes
65-46245-13	Lock Link Assy.	Overhaul	32-34-13	Boeing	737	LG		RWJ	Yes
65-46245-14	Lock Link Assy.	Overhaul	32-34-13	Boeing	737	LG		RWJ	Yes
65-46245-5	Nlg Lock Link Assy.	Overhaul	32-34-13	Boeing	737	LG		RWJ	Yes
65-46245-7	Nlg Uplock Link Assy.	Overhaul	32-34-13	Boeing	737	LG		RWJ	Yes
65-46250-10	Aft Collar Half	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46250-6	Aft Collar Half	Overhaul	32-26-01	Boeing	737	LG		RWJ	Yes
65-46250-8	Aft Collar Half	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46250-9	Aft Collar Half	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46252-5	Fwd Collar Half	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46252-7	Fwd Collar Half	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46252-8	Fwd Collar Half	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46288-11	Torsion Link	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46288-13	Torsion Link	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46288-15	Nlg Torsion Link Assy.	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46288-5	Torsion Link	Overhaul	32-26-01	Boeing	737	LG		RWJ	Yes
65-46288-9	Torsion Link	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65-46427-44	Flap Track	Overhaul	57-53-15	Boeing	737	AF		RWJ	Yes

Capabilities List

Aircraft Tooling, Inc.  
Capabilities List

Revision: 35  
Revised 01/27/12

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
65-46428-25	Flap Track	Overhaul	57-53-15	Boeing	737	AF		RWJ	Yes
65-46428-35	Flap Track Assy.	Overhaul	57-53-15	Boeing	737	AF		RWJ	Yes
65-46850-10	Saddle Mount	Overhaul	71-23-01	Boeing	737	Acc.		RWJ	Yes
65-46850-13	Saddle Mount	Overhaul	71-23-01	Boeing	737	Acc.		RWJ	Yes
65-46850-14	Saddle Mount (R/H)	Overhaul	71-23-01	Boeing	737	Acc.		RWJ	Yes
65-46850-5	Saddle Mount (L/H)	Overhaul	71-23-01	Boeing	737	Acc.		RWJ	Yes
65-46850-6	Saddle Mount	Overhaul	71-23-01	Boeing	737	Acc.		RWJ	Yes
65-46850-7	Saddle Mount (L/H)	Overhaul	71-23-01	Boeing	737	Acc.		RWJ	Yes
65-46850-8	Saddle Mount	Overhaul	71-23-01	Boeing	737	Acc.		RWJ	Yes
65-46850-9	Engine Saddle Mount	Overhaul	71-23-01	Boeing	737	Acc.		RWJ	Yes
65-47821-25	Flap Carriage	Overhaul	57-53-35	Boeing	737	AF		RWJ	Yes
65-49182-1	Thrust Link Assy.	Overhaul	71-23-01	Boeing	737	Acc.		RWJ	Yes
65-49182-10	Fitting Assy.	Overhaul	71-23-01	Boeing	737	Acc.		RWJ	Yes
65-49182-5	Thrust Link Assy.	Overhaul	71-23-01	Boeing	737	Acc.		RWJ	Yes
65-49182-9	Fitting Assy.	Overhaul	71-23-01	Boeing	737	Acc.		RWJ	Yes
65-51604-6	Quadrant	Overhaul	27-57-02	Boeing	737	AF		RWJ	Yes
65-56665-4	Shaft	Overhaul	27-17-02	Boeing	737	AF		RWJ	Yes
65-60579-3	Lower Drag Strut Assy.	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-61740-10	Mlg Outer Cylinder	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65-61740-5	Mlg Outer Cylinder	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65-63378-11	Trunnion Link	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-63378-15	Trunnion Link	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-63378-20	Trunnion Link	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-63378-3	Trunnion Link	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-63378-7	Trunnion Link	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-63378-9	Trunnion Link	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-63397-9	Lower Side Strut Assy.	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
65-63663-1	Bellcrank	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
65-63663-3	Bellcrank	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
65-63663-9	Bellcrank	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
65-63667-15	Bellcrank	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
65-63667-16	Link Assy.	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
65-63667-23	Link Assy.	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
65-63667-24	Link Assy.	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
65-63667-5	Link Assy. Matched Set	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes

Capabilities List

Aircraft Tooling, Inc.  
Capabilities List

Revision: 35  
Revised 01/27/12

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
65-63667-7	Link Assy.	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
65-63667-8	Link Assy.	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
65-67963-3	Upper Torsion Link	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
65-80051-1	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-80051-10	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-80051-11	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-80051-12	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-80051-13	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-80051-14	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-80051-18	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-80051-2	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-80051-20	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-80051-3	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-80051-4	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-80051-5	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-80051-6	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-80051-7	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-80051-8	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-80051-9	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
65-82768-1	Beam Link Assy.	Overhaul	57-41-21	Boeing	737	AF		RWJ	Yes
65-82768-2	Beam Link Assy.	Overhaul	57-41-21	Boeing	737	AF		RWJ	Yes
65-82768-4	Fwd Link Assy. ((R/H))	Overhaul	57-41-21	Boeing	737	AF		RWJ	Yes
65-82768-6	Aft Link Assy. ((R/H))	Overhaul	57-41-21	Boeing	737	AF		RWJ	Yes
65-82768-7	Beam Link Assy (L/H)	Overhaul	57-41-21	Boeing	737	AF		RWJ	Yes
65B01547-2	Bearing Housing	Repair	32-30-75	Boeing	747	LG		RWJ	Yes
65B01564	Head End	Repair	32-11-71	Boeing	747	LG		RWJ	Yes
65B01564-8	Head End	Repair	32-11-71	Boeing	747	LG		RWJ	Yes
65B01564-9	Head End	Repair	32-11-71	Boeing	747	LG		RWJ	Yes
65B05471-4	Pivot Pin	Overhaul	32-11-34	Boeing	747	LG		RWJ	Yes
65B10546-32	Door	Repair - SS	51-70-14	Boeing	747	AF		RWJ	Yes
65B81950-12	Support Assy	Repair	27-52-21	Boeing	747	AF		RWJ	Yes
65B81950-9	Support Assy.	Repair	27-52-21	Boeing	747	AF		RWJ	Yes
65B81955-4	Upper Housing	Repair	27-52-11	Boeing	747	AF		RWJ	Yes
65B81957-8	Housing	Repair	27-52-11	Boeing	747	AF		RWJ	Yes
65B81958-5	Support	Repair	27-52-42	Boeing	747	AF		RWJ	Yes

Capabilities List

Aircraft Tooling, Inc.  
Capabilities List

Revision: 35  
Revised 01/27/12

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
65B81958-6	Support	Repair	27-52-42	Boeing	747	AF		RWJ	Yes
65B81959-5	Support	Repair	27-52-42	Boeing	747	AF		RWJ	Yes
65B81982-6	Support	Repair	27-52-11	Boeing	747	AF		RWJ	Yes
65B81995-6	Lower-Assy. Housing	Repair	27-52-21	Boeing	747	AF		RWJ	Yes
65B81995-8	Housing	Repair	27-52-21	Boeing	747	AF		RWJ	Yes
65B82407-2	Housing	Repair	27-52-42	Boeing	747	AF		RWJ	Yes
65B82586-1	Piston	Repair	32-34-12	Boeing	747	LG		RWJ	Yes
65B82589-1	Head Assy.	Repair	32-34-12	Boeing	747	LG		RWJ	Yes
65B90349-4	Universal Fitting Assy.	Overhaul	71-20-01	Boeing	747	Acc.		RWJ	Yes
65C27530-4	Quadrant	Repair	32-34-17	Boeing	737	LG		RWJ	Yes
65C31332-6	Trunnion Bearing	Overhaul	32-16-31	Boeing	737	LG	1/3/2012	RWJ	Yes
65C31505-2	Shaft	Repair	27-16-11	Boeing	737	AF		RWJ	Yes
65C33654-1	Spring Bracket	Overhaul	32-34-13	Boeing	737	LG		RWJ	Yes
65C33654-2	Spring Bracket	Overhaul	32-34-13	Boeing	737	LG		RWJ	Yes
65C33654-7	Spring Bracket	Overhaul	32-34-13	Boeing	737	LG		RWJ	Yes
65C33654-8	Spring Bracket	Overhaul	32-34-13	Boeing	737	LG		RWJ	Yes
65C34776-1	(L/H) Trunnion Pin	Overhaul	32-21-38	Boeing	737	LG		RWJ	Yes
65C34809-2	Flap Track	Overhaul	57-53-15	Boeing	737	AF		RWJ	Yes
65C34810-1	Flap Track	Overhaul	57-53-15	Boeing	737	AF		RWJ	Yes
65C34812-2	Flap Track Assy.	Overhaul	57-53-15	Boeing	737	AF		RWJ	Yes
65C34812-6	Flap Track Assy.	Overhaul	57-53-15	Boeing	737	AF		RWJ	Yes
65C35162-1	Spacer	Overhaul	57-53-15	Boeing	737	AF		RWJ	Yes
65C35163-3	Spacer	Overhaul	57-53-15	Boeing	737	AF		RWJ	Yes
65C35164-1	Spacer	Overhaul	57-53-15	Boeing	737	AF		RWJ	Yes
65C35165-2	Flap Track	Overhaul	57-53-16	Boeing	737	AF		RWJ	Yes
65C35276-2	Flap Track Assy.	Overhaul	57-53-16	Boeing	737	AF		RWJ	Yes
65C36351-10	Support Tube Lower Seg.	Overhaul	57-15-01	Boeing	737	AF		RWJ	Yes
65C36351-14	Upper Segment	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65C36351-5	Orifice Support Tube	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65C36351-6	Lower Segment	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
65C36459-2	Bolt	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes
65C37814-1	Bearing Assy.	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65C37819-*	Bushing	Repair	32-21-48	Boeing	737	LG	12/5/2011	RWJ	Yes
65C37819-2	Bushing	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
65C37819-4	Bushing	Repair	32-21-48	Boeing	737	LG	8/23/2011	RWJ	Yes

Capabilities List

Aircraft Tooling, Inc.  
Capabilities List

Revision: 35  
Revised 01/27/12

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
65C37821-2	Bushing	Repair	32-21-48	Boeing	737	LG		RWJ	Yes
65C37822-1	Apex Bolt	Overhaul	32-21-48	Boeing	737	LG	11/10/2011	RWJ	Yes
69-35394-3	Pin	Repair	32-01-03	Boeing	737	LG		RWJ	Yes
69-35394-4	Pin	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
69-35396-*	Bolt	Overhaul	32-01-03	Boeing	737	LG		RWJ	Yes
69-35679-1	Retainer	Overhaul	27-09-09	Boeing	737	AF		RWJ	Yes
69-38997-7	Spring Assy.	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
69-38999-2	Shaft	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
69-38999-3	Support Shaft	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
69-38999-4	Spring Support Shaft	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
69-39461-2	Bolt	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
69-39462-3	Link Assy. Stop	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
69-39463-2	Bolt	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
69-39464-4	Bolt	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes
69-39465-10	Gland Nut	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
69-39465-18	Glandnut	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
69-39465-20	Glandnut	Overhaul	32-11-11	Boeing	737	LG		RWJ	Yes
69-39473-3	Bolt	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
69-39473-6	Bolt	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
69-39474-1	Pin	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
69-39475-1	Pin	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
69-41248-3	Trunnion Pin (R/H)	Overhaul	32-21-38	Boeing	737	LG		RWJ	Yes
69-41624-1	Bolt	Overhaul	32-17-01	Boeing	737	LG		RWJ	Yes
69-41633-1	Nut	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
69-41633-3	Nut	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
69-41633-5	Nut	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
69-41634-1	Washer	Repair	32-16-01	Boeing	737	LG		RWJ	Yes
69-41634-4	Washer	Repair	32-16-01	Boeing	737	LG		RWJ	Yes
69-51833-3	Bolt	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
69-51833-4	Bolt	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
69-51838-3	Retaining Collar	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes
69-53297-2	Shaft	Overhaul	32-34-13	Boeing	737	LG		RWJ	Yes
69-54975-1	Stud Assy.	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes
69-61785-8M	O/S Bearing Assy.	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
69-61946-1	Stabilizer Tube	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes

Capabilities List

Aircraft Tooling, Inc.  
Capabilities List

Revision: 35  
Revised 01/27/12

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
69-62779-3	Bolt	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
69-62779-4	Bolt	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
69-68148-3	Bolt	Repair	32-17-11	Boeing	737	LG		RWJ	Yes
69-68149-1	Bolt	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
69-68149-3	Bolt	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
69-68150-1	Bolt	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
69-68150-3	Bolt	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
69-68151-1	Bolt	Overhaul	32-17-11	Boeing	737	LG		RWJ	Yes
69-68151-3	Bolt	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes
69-72023-4	Pin	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
69-72698-4	Pin	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
69-72698-5	Pin	Overhaul	32-21-48	Boeing	737	LG		RWJ	Yes
69-73169-1	Fusebolt	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
69-73169-1	Fusebolt	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
69-73169-3	Fusebolt	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
69-73176-2	Trunnion Bearing Bolt	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes
69-78313-1	Nut 1/16 U/S	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
69-78313-2	Nut 1/8 U/S	Overhaul	32-16-01	Boeing	737	LG		RWJ	Yes
810SW	Kit	Repair	78-11-23	Boeing	737	Acc.	6/23/2010	RWJ	Yes
811SW	Kit	Repair	78-11-23	Boeing	737	Acc.	6/23/2010	RWJ	Yes
93853-05	Hanger	Overhaul	71-21-13	Boeing	737	Acc.		RWJ	Yes
ARG7060-509	Metering Pin	Repair	Specialized Services	MD	MD-11	LG		RWJ	Yes
AYG7173-1	Metering Pin	Repair	Specialized Services	MD	MD-11	LG		RWJ	Yes
AYG7178-503	Tube	Repair	Specialized Services	MD	MD-11	LG		RWJ	Yes
AYG7442-503	Bearing Assy.	Repair	Specialized Services	MD	MD-11	LG		RWJ	Yes
BACB30LJ20CD43	Bolt	Overhaul	32-16-31	Boeing	737	LG		RWJ	Yes
BACN10BP12ACU	Nut	Repair	71-21-37	Boeing	737	Acc.		RWJ	Yes
HFAB54-PL-109-3	Plate	Repair	Boeing Doc:PL313N3064	Boeing	757	Acc.		RWJ	Yes
HFAB54-PL-109-4	Plate	Repair	Boeing Doc:PL313N3064	Boeing	757	Acc.		RWJ	Yes
HFAB54-PL-109-5	Plate	Repair	Boeing Doc:PL313N3064	Boeing	757	Acc.		RWJ	Yes
HFAB54-PL-109-6	Plate	Repair	Boeing Doc:PL313N3064	Boeing	757	Acc.		RWJ	Yes

**Capabilities List**

**Aircraft Tooling, Inc.  
Capabilities List**

**Revision: 35  
Revised 01/27/12**

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Date	Accepted By	Self-Eval.
HFAB54-PL-109-7	Plate	Repair	Boeing Doc:PL313N3064	Boeing	757	Acc.		RWJ	Yes
HFAB54-PL-109-8	Plate	Repair	Boeing Doc:PL313N3064	Boeing	757	Acc.		RWJ	Yes
MFAB32-BU-101-75C	Bushing (65C37819-4)	Repair SS	32-21-48	Boeing	737	LG	12/5/2011	RWJ	Yes
MFAB32-BU-101-80E	Bushing (65C37821-2)	Repair SS	32-21-48	Boeing	737	LG	12/5/2011	RWJ	Yes