

Repair Station Capabilities List

(Revision 27)

July 28, 2015

**Aircraft Tooling, Inc.
FAA Certificate Number RM1R457K**

ATI Proprietary Information

The information contained in this document is ATI Proprietary Information and is disclosed in confidence. It is the property of ATI and will not be used, disclosed to others or reproduced without expressed written consent of ATI. If consent is given for reproduction in whole or in part, this notice and the notice set forth on each page of this document will appear in any such reproduction in whole or in part. The U.S. export control laws may also control the information contained in this document.

Unauthorized export or re-export is prohibited

Capabilities List for Aircraft Tooling, Inc.

PURPOSE:

Establish a FAA Accepted Capabilities List

GENERAL:

According to current regulations, certified repair stations require acceptance from the FAA to perform maintenance functions. This procedure establishes ratings, limited ratings and specialized services for which this repair station is approved.

FUNCTION:

The President is required to coordinate any modification to this list with the Quality Control Manager. The administrator will accept list by signing the first page of this Capabilities List. The revision process is carried out in accordance with Section 5 of the Repair Station & Quality Control Manual (RS/QCM).

SELF-EVALUATION

Prior to adding a component to the Capabilities List, a self-evaluation audit is conducted by the Quality Control Manager or Chief Inspector to determine if ATI has the required capabilities to perform maintenance. The evaluation is recorded using the Capabilities Self Evaluation Audit Form (ATI Form CSE). Please refer to Section 5 of the RS/QCM for detailed procedures related to this process. An example of the self-evaluation form is located in the Repair Station & Quality Control Forms Manual (RS/QCFM).

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
251U3319-3	Torque Tube Assy.	Repair	27-21-44	Boeing	747	AF	Yes	4/5/2006	RWJ
R013KDJ165-1	Tube Assembly	Repair	32-21-03	Boeing	777	LG	Yes	4/29/2009	RWJ
C8512-OP1	Pin	Repair	57-15-01	Boeing	737	LG	Yes	6/18/2009	RWJ
TL10589-107	Latch Assembly	Repair	71-11-36	Boeing	777	Acc.	Yes	8/24/2009	RWJ
697039301	Rear Hub Half	Repair	61-10-43	Dowty	C-130	Prop.	Yes	6/23/2010	RWJ
697039314	Prop Hub	Repair	61-10-43	Dowty	C-130	Prop.	Yes	6/23/2010	RWJ
697070241	Prop Hub	Repair	31-10-49	Dowty	C-130	AF	Yes	6/23/2010	RWJ
113A8700-1	Center Door Rod Assy.	Repair	32-13-23	Boeing	737	LG	Yes	6/23/2010	RWJ
113A8700-*	Center Door Rod Assy.	Repair	32-13-23	Boeing	737	LG	Yes	6/23/2010	RWJ
115A1500-*	Beam Support Link	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
115A1500-13	Beam Support Link	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
115A1500-14	Beam Support Link	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
115A1610-1	Pin	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
115A1610-*	Pin	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
115A5005-1	FWD Trunnion Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
115A5005-*	FWD Trunnion Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
115A5240-1	Housing Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
115A5240-*	Housing Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
115A5260-1	Trunnion Support Pin	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
115A5260-*	Trunnion Support Pin	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
115A5280-1	Fuse Pin Retention Cap	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
115A5280-*	Fuse Pin Retention Cap	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
115A5281-1	Lube Extension	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
115A5281-1	Lube Extension	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
115A5283-1	Nut	Repair	57-15-01	Boeing	737	AF	Yes	12/22/2015	RWJ
115A5283-*	Nut	Repair	57-15-01	Boeing	737	AF	Yes	12/22/2015	RWJ
115A5284-1	Rod	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
115A5284-*	Rod	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A0101-1	Ring Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A0101-*	Ring Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1127-1	Brake Sleeve	Overhaul	32-11-12	Boeing	737	LG	Yes	6/23/2010	RWJ
161A1127-*	Brake Sleeve	Overhaul	32-11-12	Boeing	737	LG	Yes	6/23/2010	RWJ
161A1140-1	Upper Torsion Link (Titanium)	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
161A1140-*	Upper Torsion Link (Titanium)	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
161A1142-1	Torsion Link (Titanium Part)	Overhaul	32-11-12	Boeing	737	LG	Yes	6/23/2010	RWJ
161A1142-*	Torsion Link (Titanium Part)	Overhaul	32-11-12	Boeing	737	LG	Yes	6/23/2010	RWJ
161A1146-1	Pin	Overhaul	32-11-12	Boeing	737	LG	Yes	6/23/2010	RWJ
161A1146-*	Pin	Overhaul	32-11-12	Boeing	737	LG	Yes	6/23/2010	RWJ
161A1154-1	Gland Nut	Overhaul	32-11-12	Boeing	737	LG	Yes	6/23/2010	RWJ
161A1154-*	Gland Nut	Overhaul	32-11-12	Boeing	737	LG	Yes	6/23/2010	RWJ
161A1167-*	Carrier (Titanium Part)	Repair	32-11-12	Boeing	737	LG	Yes	6/23/2010	RWJ
161A1167-4	Carrier (Titanium Part)	Repair	32-11-12	Boeing	737	LG	Yes	6/23/2010	RWJ
161A1168-1	Bearing Carrier	Repair	32-11-12	Boeing	737	LG	Yes	6/23/2010	RWJ
161A1168-*	Bearing Carrier	Repair	32-11-12	Boeing	737	LG	Yes	6/23/2010	RWJ
161A1185-1	FWD Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1185-*	FWD Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1185-3	FWD Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1185-5	FWD Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1185-7	FWD Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1185-9	FWD Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1187-1	Race	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1187-*	Race	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1188-1	Trunnion Pin Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1188-10	Trunnion Pin Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1188-*	Trunnion Pin Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1188-2	Trunnion Pin	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1188-3	Trunnion Pin Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1188-4	Trunnion Pin	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1188-5	Trunnion Pin Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1188-6	Trunnion Pin	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1188-7	Trunnion Pin Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1188-8	Trunnion Pin	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1194-1	Retaining Ring	Overhaul	32-11-09	Boeing	737	LG	Yes	6/23/2010	RWJ
161A1194-*	Retaining Ring	Overhaul	32-11-09	Boeing	737	LG	Yes	6/23/2010	RWJ
161A1203-1	Nut-Retainer	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1203-*	Nut-Retainer	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1214-*	Apex Pin	Overhaul	32-11-12	Boeing	737	LG	Yes	6/23/2010	RWJ
161A1214-3	Apex Pin	Overhaul	32-11-12	Boeing	737	LG	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
161A1500-1	AFT Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1500-*	AFT Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1500-2	AFT Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1500-3	AFT Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1500-4	AFT Trunnion Bearing Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1501-1	Outer Race (Titanium)	Overhaul	57-15-04	Boeing	737	AF	Yes	12/22/2015	RWJ
161A1501-*	Outer Race (Titanium)	Overhaul	57-15-04	Boeing	737	AF	Yes	12/22/2015	RWJ
161A1501-2	Outer Race (Titanium)	Overhaul	57-15-04	Boeing	737	AF	Yes	12/22/2015	RWJ
161A1502-1	Split Ball Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1502-*	Split Ball Assy.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1503-1	Lock Plate	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1503-*	Lock Plate	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1503-2	Lock Plate	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1504-1	Retaining Nut	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1504-*	Retaining Nut	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1505-1	Locking Tab	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A1505-*	Locking Tab	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
161A2331-1	Pin	Overhaul	32-11-09	Boeing	737	LG	Yes	6/23/2010	RWJ
161A2331-*	Pin	Overhaul	32-11-09	Boeing	737	LG	Yes	6/23/2010	RWJ
161A7000-*	Actuator Pin	Overhaul	32-32-27	Boeing	737	LG	Yes	6/23/2010	RWJ
161A7000-3	Actuator Pin	Overhaul	32-32-27	Boeing	737	LG	Yes	6/23/2010	RWJ
161A7118-1	Pin	Overhaul	32-32-27	Boeing	737	LG	Yes	6/23/2010	RWJ
161A7118-*	Pin	Overhaul	32-32-27	Boeing	737	LG	Yes	6/23/2010	RWJ
161A7118-2	Pin	Overhaul	32-32-27	Boeing	737	LG	Yes	6/23/2010	RWJ
161N1258	Metering Pin	Overhaul	32-11-95	Boeing	757	LG	Yes	6/23/2010	RWJ
161N1258-1	Metering Pin	Overhaul	32-11-95	Boeing	757	LG	Yes	6/23/2010	RWJ
161N1258-*	Metering Pin	Overhaul	32-11-95	Boeing	757	LG	Yes	6/23/2010	RWJ
161N1621-1	Tow Fitting	Overhaul	32-11-56	Boeing	757	LG	Yes	6/23/2010	RWJ
161N1621-*	Tow Fitting	Overhaul	32-11-56	Boeing	757	LG	Yes	6/23/2010	RWJ
161N1621-2	Tow Fitting	Overhaul	32-11-56	Boeing	757	LG	Yes	6/23/2010	RWJ
161T1133-*	Tow Fitting	Overhaul	32-11-50	Boeing	767	LG	Yes	6/23/2010	RWJ
161T1133-3	Tow Fitting	Overhaul	32-11-50	Boeing	767	LG	Yes	6/23/2010	RWJ
161T1190-1	AFT Race Assy.	Overhaul	32-11-81	Boeing	767	LG	Yes	6/23/2010	RWJ
161T1190-*	AFT Race Assy.	Overhaul	32-11-81	Boeing	767	LG	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
161T2106-*	Spindle	Overhaul	32-11-81	Boeing	767	LG	Yes	6/23/2010	RWJ
161T2106-2	Spindle	Overhaul	32-11-81	Boeing	767	LG	Yes	6/23/2010	RWJ
161T2106-3	Spindle	Overhaul	32-11-81	Boeing	767	LG	Yes	6/23/2010	RWJ
161T2108-1	Lower Spindle	Overhaul	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T2108-*	Lower Spindle	Overhaul	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T2108-2	Lower Spindle	Overhaul	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T2875-1	Bushing	Repair	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T2875-*	Bushing	Repair	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T2875-3	Bushing	Repair	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T2877-*	Bushing	Repair	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T2877-2	Bushing	Repair	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T6105-*	Lower Spindle	Overhaul	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T6105-2	Lower Spindle	Overhaul	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T6107-*	Spindle	Overhaul	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T6107-2	Spindle	Overhaul	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T7125-1	Torsion Pin	Overhaul	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T7125-*	Torsion Pin	Overhaul	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T7125-2	Torsion Pin	Overhaul	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T7133-*	MLG Axle	Overhaul	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T7133-2	MLG Axle	Overhaul	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T7140-1	Brake Rod Pin	Overhaul	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T7140-*	Brake Rod Pin	Overhaul	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T7140-2	Brake Rod Pin	Overhaul	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T7193-1	Pivot Pin	Overhaul	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161T7193-*	Pivot Pin	Overhaul	32-11-36	Boeing	767	LG	Yes	6/23/2010	RWJ
161W1345-*	Race	Repair	32-11-07	Boeing	777	LG	Yes	6/23/2010	RWJ
161W1345-2	Race	Repair	32-11-07	Boeing	777	LG	Yes	6/23/2010	RWJ
162A0301-1	Trunnion Pin	Overhaul	32-21-07	Boeing	737	LG	Yes	6/23/2010	RWJ
162A0301-*	Trunnion Pin	Overhaul	32-21-07	Boeing	737	LG	Yes	6/23/2010	RWJ
162A0302-1	Trunnion Pin	Overhaul	32-21-07	Boeing	737	LG	Yes	6/23/2010	RWJ
162A0302-*	Trunnion Pin	Overhaul	32-21-07	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1160-1	Tow Fitting Assy.	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1160-*	Tow Fitting Assy.	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1160-5	Tow Fitting	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
162A1306-1	Pin	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1306-*	Pin	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1310-1	Pin	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1310-*	Pin	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1311-1	Upper Torsion Link	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1311-*	Upper Torsion Link	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1312-1	Lower Torsion Link	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1312-*	Lower Torsion Link	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1313-1	Lower Torsion Link Assy.	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1313-*	Lower Torsion Link Assy.	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1315-1	Upper Torsion Link Assy.	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1315-*	Upper Torsion Link Assy.	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1404-*	Steering Collar Assy.	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1404-3	Steering Collar Assy.	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1404-4	Steering Collar Assy.	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1405-*	Steering Sleeve (Titanium)	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1405-5	Steering Sleeve (Titanium)	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1405-6	Steering Sleeve (Titanium)	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1411-1	Pin	Overhaul	32-21-16	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1411-*	Pin	Overhaul	32-21-16	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1417-*	Steering Plate (Titanium)	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1417-4	Steering Plate (Titanium)	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1417-5	Steering Plate (Titanium)	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1417-6	Steering Plate (Titanium)	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1420-1	Steering Collar	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1420-*	Steering Collar	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1421-1	Steering Sleeve (Titanium)	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1421-*	Steering Sleeve (Titanium)	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1421-2	Steering Sleeve (Titanium)	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1421-4	Steering Sleeve (Titanium)	Repair	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1501-1	Lower Centering Cam	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1501-*	Lower Centering Cam	Overhaul	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1510-1	Lower Bearing Carrier	Repair	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1510-*	Lower Bearing Carrier	Repair	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
162A1511-*	Upper Bearing Carrier	Repair	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A1511-4	Upper Bearing Carrier	Repair	32-21-12	Boeing	737	LG	Yes	6/23/2010	RWJ
162A2115-*	Link Assy. AFT	Overhaul	32-21-22	Boeing	737	LG	Yes	6/23/2010	RWJ
162A2115-5	Link Assy. AFT	Overhaul	32-21-22	Boeing	737	LG	Yes	6/23/2010	RWJ
162A2301-1	Trunnion Pin Assy.	Overhaul	32-21-07	Boeing	737	LG	Yes	6/23/2010	RWJ
162A2301-*	Trunnion Pin Assy.	Overhaul	32-21-07	Boeing	737	LG	Yes	6/23/2010	RWJ
162A2301-2	Trunnion Pin	Overhaul	32-21-07	Boeing	737	LG	Yes	6/23/2010	RWJ
162A2302-1	Pin	Overhaul	32-21-07	Boeing	737	LG	Yes	6/23/2010	RWJ
162A2302-*	Pin	Overhaul	32-21-07	Boeing	737	LG	Yes	6/23/2010	RWJ
162W1400-*	Tube Assy.	Repair	32-21-03	Boeing	777	LG	Yes	6/23/2010	RWJ
162W1400-2	Tube Assy.	Repair	32-21-03	Boeing	777	LG	Yes	6/23/2010	RWJ
162W1402-*	Lower Steering Plate	Repair	32-21-03	Boeing	777	LG	Yes	6/23/2010	RWJ
162W1402-2	Lower Steering Plate/Tube Assy.	Repair	32-21-03	Boeing	777	LG	Yes	6/23/2010	RWJ
173-1034-*	Idler Link Assy.	Repair	78-30-12	Boeing	737	Acc.	Yes	6/23/2010	RWJ
173-1034-5	Idler Link Assy.	Repair	78-30-12	Boeing	737	Acc.	Yes	6/23/2010	RWJ
256T3438-*	Housing	Repair	27-51-37	Boeing	767	AF	Yes	6/23/2010	RWJ
256T3438-2	Housing	Repair	27-51-37	Boeing	767	AF	Yes	6/23/2010	RWJ
256W2243-*	Housing	Repair	27-81-67	Boeing	777	AF	Yes	6/23/2010	RWJ
256W2243-2	Housing	Repair	27-81-67	Boeing	777	AF	Yes	6/23/2010	RWJ
273N2037-*	Barrel	Overhaul	32-32-56	Boeing	757	LG	Yes	6/23/2010	RWJ
273N2037-2	Barrel	Overhaul	32-32-56	Boeing	757	LG	Yes	6/23/2010	RWJ
273N2037-3	Barrel Assy.	Overhaul	32-32-56	Boeing	757	LG	Yes	6/23/2010	RWJ
273N2041-1	Rod End Assy.	Overhaul	32-32-56	Boeing	757	LG	Yes	6/23/2010	RWJ
273N2041-*	Rod End Assy.	Overhaul	32-32-56	Boeing	757	LG	Yes	6/23/2010	RWJ
273N2041-2	Rod End	Overhaul	32-32-56	Boeing	757	LG	Yes	6/23/2010	RWJ
273T0065-*	End Head	Repair	32-34-00	Boeing	767	LG	Yes	6/23/2010	RWJ
273T0065-2	End Head	Repair	32-34-00	Boeing	767	LG	Yes	6/23/2010	RWJ
273T1105-1	Head End	Repair	32-32-00	Boeing	767	LG	Yes	6/23/2010	RWJ
273T1105-*	Head End	Repair	32-32-00	Boeing	767	LG	Yes	6/23/2010	RWJ
273T4117-*	Head End	Repair	32-34-00	Boeing	767	LG	Yes	6/23/2010	RWJ
273T4117-2	Head End	Repair	32-34-00	Boeing	767	LG	Yes	6/23/2010	RWJ
275N1228	Trunnion	Overhaul	32-51-15	Boeing	757	LG	Yes	6/23/2010	RWJ
275N1228-1	Trunnion	Overhaul	32-51-15	Boeing	757	LG	Yes	6/23/2010	RWJ
275N1228-*	Trunnion	Overhaul	32-51-15	Boeing	757	LG	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
275N1228-3	Trunnion	Overhaul	32-51-15	Boeing	757	LG	Yes	6/23/2010	RWJ
275T6223	Trunnion	Repair	32-51-10	Boeing	767	LG	Yes	6/23/2010	RWJ
275T6223-1	Trunnion	Repair	32-51-10	Boeing	767	LG	Yes	6/23/2010	RWJ
275T6223-*	Trunnion	Repair	32-51-10	Boeing	767	LG	Yes	6/23/2010	RWJ
295W1702-*	Trunnion	Repair	32-51-13	Boeing	777	LG	Yes	6/23/2010	RWJ
295W1702-3	Trunnion	Repair	32-51-13	Boeing	777	LG	Yes	6/23/2010	RWJ
310A1020-11	Eng. Mount Assy.	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1020-*	Eng. Mount Assy.	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1020-14	AFT Mount Assy.	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1020-20	Thrust Link Assy.	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1020-21	AFT Engine Mount Assy.	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1020-22	AFT Engine Mount	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1020-26	AFT Mount Assy.	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1020-3	AFT Engine Mount Assy.	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1021-1	Mount	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1021-*	Mount	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1021-2	Mount	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1022-1	Crossbeam Assy.	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1022-*	Crossbeam Assy.	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1022-7	Crossbeam	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1023-1	Link Assy.	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1023-*	Link Assy.	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1023-2	Link Assy.	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1025-1	Fitting	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1025-*	Fitting	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1026-1	Failsafe Fitting	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1026-*	Failsafe Fitting	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1028-1	Hanger	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1028-*	Hanger	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1028-7	Hanger	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1031-1	Pin	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1031-*	Pin	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1032-*	Link Assy.	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1032-3	Link Assy.	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
310A1032-5	Link Assy.	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1033-1	Evener Bar	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1033-*	Evener Bar	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1033-3	Evener Bar	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1033-5	Evener Bar	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1035-1	Shear Pin	Repair	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1035-*	Shear Pin	Repair	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1036-1	Thrust Link Mount	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1036-12	Shouldered Bolt	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1036-*	Thrust Link Mount	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1036-2	Thrust Link Mount	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1036-5	Thrust Link	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1036-6	Fitting Assy.	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1039-*	Bolt Retainer	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1039-7	Bolt Retainer	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1041-1	Cone Bolt	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1041-*	Cone Bolt	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1041-2	Cone Bolt	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1041-5	Cone Bolt Assy.	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1041-7	Cone Bolt	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1043-*	Bolt	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A1043-3	Bolt	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2020-10	FWD Engine Mount Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2020-11	Forward Mount Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2020-*	FWD Engine Mount Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2020-5	FWD Engine Mount	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2020-6	Shear Bushing	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2021-*	Fitting Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2021-4	Fitting Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2022-*	Link Assy. FWD.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2022-3	Link Assy. FWD.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2024-*	Shear Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2024-2	Shear Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2028-11	Fitting Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
310A2028-*	Fitting Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2028-13	Fitting Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2029-11	Bolt	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2029-*	Bolt	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2029-19	Bolt	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2030-11	AFT Engine Mount Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2030-*	AFT Engine Mount Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2030-15	AFT Engine Mount Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2030-17	AFT Engine Mount	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2030-6	AFT Engine Mount	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2031-*	Hanger Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2031-22	Hanger Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2031-23	Hanger Assy.	Repair	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2031-24	Hanger Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2031-9	Hanger Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2033-*	Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2033-3	Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2033-5	Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2033-7	Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2033-8	Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2034-*	Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2034-13	Center Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2034-14	Link Assy. - Ctr	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2034-3	Link Assy. - Ctr	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2034-4	Link Assy	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2034-7	Center Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2034-8	Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2035-*	Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2035-3	Right Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2035-5	Link Assy.-Right	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2035-7	Link Assy.	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2035-8	Link Assy. (R/H)	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2036-*	Evener Bar	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2036-5	Evener Bar	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
310A2036-8	Evener Bar	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2037-10	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2037-11	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2037-12	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2037-*	Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2037-13	Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2037-14	Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2037-15	Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2037-16	Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2037-4	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2037-5	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2037-6	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2037-7	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2037-8	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2037-9	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2039-1	End Cap	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2039-*	End Cap	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2039-2	End Cap	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2039-3	End Cap	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2041-10	Thrust Link Assy.	Overhaul	71-04-26	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2041-*	Thrust Link Assy.	Overhaul	71-04-26	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2041-5	Thrust Link Assy.	Overhaul	71-04-26	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2041-6	Link Assy.	Overhaul	71-04-26	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2041-9	Thrust Link Assy.	Overhaul	71-04-26	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2042-*	Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2042-2	Pawl Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2042-3	Pin	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2043-1	End Cap	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310A2043-*	End Cap	Overhaul	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
310N3021-*	Fitting	Overhaul	71-21-15	Boeing	757	Acc.	Yes	6/23/2010	RWJ
310N3021-2	Fitting	Overhaul	71-21-15	Boeing	757	Acc.	Yes	6/23/2010	RWJ
310N3021-5	Fitting	Overhaul	71-21-15	Boeing	757	Acc.	Yes	6/23/2010	RWJ
310N3036-*	Shouldered Bolt	Overhaul	71-21-15	Boeing	757	Acc.	Yes	6/23/2010	RWJ
310N3036-2	Shouldered Bolt	Overhaul	71-21-15	Boeing	757	Acc.	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
310T1036-*	Bolt	Overhaul	71-21-13	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310T1036-19	Bolt	Overhaul	71-21-13	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310T1036-22	Bolt-Shoulder	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310T1036-23	Bolt-Shoulder	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310T1036-24	Bolt-Shoulder	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310T1036-7	Shouldered Bolt	Overhaul	71-21-13	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310T3037-*	Pin-Shear	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310T3037-2	Pin-Shear	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310T3151-*	Washer-Special	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310T3151-18	Washer-Special	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310T3151-19	Washer-Special	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310T4012-*	Hinge Pin	Overhaul	71-21-16	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310T4012-2	Hinge Pin	Overhaul	71-21-16	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310T4021-1	Fitting Assy.	Overhaul	71-21-16	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310T4021-*	Fitting Assy.	Overhaul	71-21-16	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310T4021-2	Fitting	Overhaul	71-21-16	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310T4021-3	Fitting	Repair	71-21-16	Boeing	747	Acc.	Yes	6/23/2010	RWJ
310T4021-4	Fitting	Overhaul	71-21-16	Boeing	747	Acc.	Yes	6/23/2010	RWJ
310T4021-5	Fitting	Overhaul	71-21-16	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310T4038-1	Shear Pin	Overhaul	71-21-16	Boeing	747	Acc.	Yes	6/23/2010	RWJ
310T4038-*	Shear Pin	Overhaul	71-21-16	Boeing	747	Acc.	Yes	6/23/2010	RWJ
310U2020-*	AFT Engine Mount Assy	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310U2020-18	AFT Engine Mount Assy	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310U2031-*	Upper Fitting Assy.	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310U2031-23	Upper Fitting Assy.	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310U2032-*	Link Assy.	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310U2032-3	Link Assy.	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310U2033-*	Lower Fitting Assy.	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310U2033-25	Lower Fitting Assy.	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310U2033-27	Lower Fitting Assy.	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310U2039-1	Retainer-Bolt	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310U2039-*	Retainer-Bolt	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310U2039-2	Retainer-Bolt	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ
310U2039-5	Retainer-Bolt	Overhaul	71-21-14	Boeing	767	Acc.	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
310W3020-*	Fitting	Repair	71-21-21	Boeing	777	Acc.	Yes	6/23/2010	RWJ
310W3020-4	Fitting	Repair	71-21-21	Boeing	777	Acc.	Yes	6/23/2010	RWJ
310W3021-*	Fitting Assy.	Overhaul	71-21-21	Boeing	777	Acc.	Yes	6/23/2010	RWJ
310W3021-5	Fitting Assy.	Overhaul	71-21-21	Boeing	777	Acc.	Yes	6/23/2010	RWJ
310W3023-*	Thrust Link Assy.	Repair	71-21-21	Boeing	777	Acc.	Yes	6/23/2010	RWJ
310W3023-5	Thrust Link Assy.	Repair	71-21-21	Boeing	777	Acc.	Yes	6/23/2010	RWJ
310W3035-*	Pin	Repair	71-21-21	Boeing	777	Acc.	Yes	6/23/2010	RWJ
310W3035-5	Pivot Pin	Repair	71-21-21	Boeing	777	Acc.	Yes	6/23/2010	RWJ
310W3035-6	Link Pin	Repair	71-21-21	Boeing	777	Acc.	Yes	6/23/2010	RWJ
311A1090-1	Pin	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
311A1090-*	Pin	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
311A1090-2	Pin	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
311A1091-1	Pin	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
311A1091-*	Pin	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
311A1092-*	Fuse Pin	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
311A1092-2	Fuse Pin	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
311A1562-*	Cross Beam	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
311A1562-2	Cross Beam	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
311A1562-5	Cross Beam	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
311A1562-6	Cross Beam	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
311A1710-*	Pylon Link	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
311A1710-5	Pylon Link	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
311A1710-8	Pylon Link	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
311A1730-1	Brace Assy.	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
311A1730-*	Brace Assy.	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
311A1730-5	Brace Assy.	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
311A1730-7	Brace Assy.	Overhaul	54-50-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
314A1502-*	Exhaust Seal Assy.	Overhaul	78-11-23	Boeing	737	Acc.	Yes	6/23/2010	RWJ
314A1502-38	L/H Support	Overhaul	78-11-23	Boeing	737	Acc.	Yes	6/23/2010	RWJ
314A1502-39	Support Assy.	Overhaul	78-11-23	Boeing	737	Acc.	Yes	6/23/2010	RWJ
314A1502-40	Exhaust Seal	Overhaul	78-11-23	Boeing	737	Acc.	Yes	6/23/2010	RWJ
314A1502-41	Exhaust Seal Assy.	Overhaul	78-11-23	Boeing	737	Acc.	Yes	6/23/2010	RWJ
314A1502-52	Exhaust Seal	Overhaul	78-11-23	Boeing	737	Acc.	Yes	6/23/2010	RWJ
314A1502-53	Exhaust Seal	Overhaul	78-11-23	Boeing	737	Acc.	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
314A1502-60	Exhaust Seal	Overhaul	78-11-23	Boeing	737	Acc.	Yes	6/23/2010	RWJ
314A1502-61	Exhaust Seal	Overhaul	78-11-23	Boeing	737	Acc.	Yes	6/23/2010	RWJ
314W1300-*	Fan Cowl Beam Assy.	Repair	71-11-08	Boeing	777	Acc.	Yes	6/23/2010	RWJ
314W1300-8	Fan Cowl Beam Assy.	Repair	71-11-08	Boeing	777	Acc.	Yes	6/23/2010	RWJ
315A1511-1	Link Assy.	Repair	78-31-23	Boeing	737	Acc.	Yes	6/23/2010	RWJ
315A1511-*	Link Assy.	Repair	78-31-23	Boeing	737	Acc.	Yes	6/23/2010	RWJ
332A1908-*	Deflector Assy.	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
332A1908-54	Deflector Assy.	Overhaul	71-21-13	Boeing	737	Acc.	Yes	6/23/2010	RWJ
335-106-403-0	Spinner Cone	Repair	70-44-10	CFM	737	Acc.	Yes	6/23/2010	RWJ
335-106-403-*	Spinner Cone	Repair	70-44-10	Boeing	737	Acc.	Yes	6/23/2010	RWJ
337-005-118-0	Spinner Cone	Repair	70-44-10	CFM	737	Acc.	Yes	6/23/2010	RWJ
337-005-118-*	Spinner Cone	Repair	70-44-10	Boeing	737	Acc.	Yes	6/23/2010	RWJ
352A1200-*	Strut Assy.	Repair	49-13-12	Boeing	737	AF	Yes	6/23/2010	RWJ
352A1200-31	Strut Assy.	Repair	49-13-12	Boeing	737	AF	Yes	6/23/2010	RWJ
352A1200-32	Strut Assy.	Repair	49-13-12	Boeing	737	AF	Yes	6/23/2010	RWJ
65-2199-*	Trunnion Assy.	Repair	32-08-01	Boeing	707	LG	Yes	6/23/2010	RWJ
65-44711-*	Steering Barrel	Overhaul	32-50-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-44711-5	Steering Barrel	Overhaul	32-50-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46102-*	Lower Torsion Link	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46102-21	Lower Torsion Link	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46102-23	Lower Torsion Link	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46103-*	Upper Drag Strut	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46103-13	Upper Drag Strut	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46106-11	Universal Assy.	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46106-*	Universal Assy.	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46106-7	Universal Assy.	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46106-8	Universal	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46106-9	Universal	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46107-1	Universal Assy.	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46107-*	Universal Assy.	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46108-*	Actuator Beam	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46108-17	Actuator Beam	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46108-19	Actuator Beam Assy.	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46108-3	Actuator Beam	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
65-46109-12	Arm	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46109-*	MLG Actuator Beam Arm	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46109-14	MLG Actuator Beam Arm	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46109-14L	Arm	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46109-18	Arm	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46109-20	Actuator Beam Arm	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46112-*	MLG Support Link	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46112-19	MLG Support Link	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46112-22	Support Link	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46112-30	Support Link	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46113-12	Trunnion Pin	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46113-*	Trunnion Pin	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46113-16	Trunnion Pin	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46113-19	Trunnion Pin	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46113-21	Trunnion Pin	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46113-23	Trunnion Pin	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46113-25	MLG Trunnion Pin	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46124-1	Metering Pin	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46124-*	Metering Pin	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46124-3	Metering Pin	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46124-5	Metering Pin	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46133-*	Up Side Strut Assy.	Overhaul	32-12-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46133-5	Up Side Strut Assy.	Overhaul	32-12-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46135-*	Reaction Link Assy.	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46135-13	Reaction Link Assy.	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46135-20	Reaction Link Assy.	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46138-10	Downlock Link Assy.	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46138-*	Downlock Link Assy.	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46138-23	Downlock Link	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46139-*	Link Assy.	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46139-14	Link Assy.	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46139-9	Lower Downlock Link	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46140-*	Tee Bolt	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46140-6	Tee Bolt	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
65-46140-7	Tee Bolt Fitting	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46140-9	Tee Bolt	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46141-11	(L/H) Uplock Assy.	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46141-12	(R/H) Uplock Assy.	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46141-*	Uplock Assy.	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46141-17	L/H Uplock Assy.	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46141-18	(R/H) Uplock Assy.	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46141-21	MLG Uplock Assy.	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46141-22	MLG Uplock Assy.	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46142-*	Uplock Hook	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46142-7	Uplock Hook	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46146-1	Support Shaft	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46146-*	Support Shaft	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46146-2	Support Shaft	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46146-3	Support Shaft	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46146-4	Support Shaft	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46147	Axle Sleeve	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46156-1	Drain Tube	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46156-*	MLG Drain Tube	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46156-3	MLG Drain Tube	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46156-5	Drain Tube	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46159-*	M.L.G. Support Tube	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46159-7	M.L.G. Support Tube	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46159-9	Orifice Tube	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46160-10	Support Tube	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46160-11	Support Tube	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46160-*	Support Tube	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46160-8	Support Tube	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46160-9	Orifice Support Tube	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46202-*	Upper Torsion Link	Overhaul	32-26-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46202-9	Upper Torsion Link	Overhaul	32-26-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46203	Steering Collar	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46203-*	Steering Collar	Overhaul	32-21-48 & 32-26-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46203-20	Steering Collar	Overhaul	32-26-01	Boeing	737	LG	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
65-46203-20M	Steering Collar	Overhaul	32-26-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46203-24	Steering Collar	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46203-24M	Steering Collar	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46203-25	Steering Collar Assy.	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46203-26	Steering Collar	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46203-26M	Steering Collar	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46203-27	Steering Collar	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46203-28	Steering Collar	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46203-29	Steering Collar	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46203-29M	Steering Collar	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46203-31	Steering Collar	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46203-31M	Steering Collar	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46210-*	Steering Plate	Overhaul	32-21-58	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46210-33	Upper Steering Plate	Overhaul	32-21-58	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46210-34	Lower Steering Plate	Overhaul	32-32-27	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46211-*	NLG Outer Cylinder	Overhaul	32-21-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46211-7	NLG Outer Cylinder	Overhaul	32-21-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46211-8	NLG Outer Cylinder	Overhaul	32-21-16	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46215-12	NLG Inner Cylinder	Overhaul	32-21-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46215-*	NLG Inner Cylinder	Overhaul	32-21-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46215-13	Inner Cylinder	Overhaul	32-21-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46219-1	Metering Pin	Overhaul	32-12-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46219-*	Metering Pin	Overhaul	32-21-58	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46219-2	Metering Pin	Overhaul	32-21-58	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46221-11	Gland Nut	Overhaul	32-21-58	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46221-12	Gland Nut	Overhaul	32-21-58	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46221-*	Gland Nut	Overhaul	32-21-58	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46227-1	Upper Centering Cam	Overhaul	32-21-58	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46227-*	Upper Centering Cam	Overhaul	32-21-58	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46228-*	Lower Centering Cam	Overhaul	32-21-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46228-3	Lower Centering Cam	Overhaul	32-21-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46230-1	Lower Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46230-11	Lower Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46230-*	Lower Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
65-46230-13	Lower Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46230-15	Lower Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46230-5	Lower Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46230-7	Lower Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46240-11	Brace Assy.	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46240-*	Brace Assy.	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46240-13	Lock Brace Assy.	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46240-15	Lock Brace Assy.	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46242-11	Lock Link Assy.	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46242-*	Lock Link Assy.	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46242-13	Lock Link Assy.	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46245-11	NLG Lock Link Assy.	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46245-*	NLG Lock Link Assy.	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46245-13	Lock Link Assy.	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46245-14	Lock Link Assy.	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46245-5	NLG Lock Link Assy.	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46245-7	NLG Uplock Link Assy.	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46250-10	AFT Collar Half	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46250-*	AFT Collar Half	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46250-6	AFT Collar Half	Overhaul	32-26-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46250-8	AFT Collar Half	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46250-9	AFT Collar Half	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46252-*	FWD Collar Half	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46252-5	FWD Collar Half	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46252-7	FWD Collar Half	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46252-8	FWD Collar Half	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46288-11	Torsion Link	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46288-*	Torsion Link	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46288-13	Torsion Link	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46288-15	NLG Torsion Link Assy.	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46288-5	Torsion Link	Overhaul	32-26-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46288-9	Torsion Link	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
65-46427-*	Flap Track	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65-46427-44	Flap Track	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
65-46428-*	Flap Track	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65-46428-25	Flap Track	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65-46428-35	Flap Track Assy.	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65-46850-10	Saddle Mount	Overhaul	71-23-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
65-46850-*	Saddle Mount	Overhaul	71-23-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
65-46850-13	Saddle Mount	Overhaul	71-23-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
65-46850-14	Saddle Mount (R/H)	Overhaul	71-23-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
65-46850-5	Saddle Mount (L/H)	Overhaul	71-23-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
65-46850-6	Saddle Mount	Overhaul	71-23-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
65-46850-7	Saddle Mount (L/H)	Overhaul	71-23-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
65-46850-8	Saddle Mount	Overhaul	71-23-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
65-46850-9	Engine Saddle Mount	Overhaul	71-23-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
65-47821-*	Flap Carriage	Overhaul	57-53-35	Boeing	737	AF	Yes	6/23/2010	RWJ
65-47821-25	Flap Carriage	Overhaul	57-53-35	Boeing	737	AF	Yes	6/23/2010	RWJ
65-49182-1	Thrust Link Assy.	Overhaul	71-23-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
65-49182-10	Fitting Assy.	Overhaul	71-23-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
65-49182-*	Thrust Link Assy.	Overhaul	71-23-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
65-49182-5	Thrust Link Assy.	Overhaul	71-23-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
65-49182-9	Fitting Assy.	Overhaul	71-23-01	Boeing	737	Acc.	Yes	6/23/2010	RWJ
65-51604-*	Quadrant	Overhaul	27-57-02	Boeing	737	AF	Yes	6/23/2010	RWJ
65-51604-6	Quadrant	Overhaul	27-57-02	Boeing	737	AF	Yes	6/23/2010	RWJ
65-56665-*	Shaft	Overhaul	27-17-02	Boeing	737	AF	Yes	6/23/2010	RWJ
65-56665-4	Shaft	Overhaul	27-17-02	Boeing	737	AF	Yes	6/23/2010	RWJ
65-60579-*	Lower Drag Strut Assy.	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-60579-3	Lower Drag Strut Assy.	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-61740-10	MLG Outer Cylinder	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-61740-*	MLG Outer Cylinder	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-61740-5	MLG Outer Cylinder	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63378-11	Trunnion Link	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63378-*	Trunnion Link	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63378-15	Trunnion Link	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63378-20	Trunnion Link	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63378-3	Trunnion Link	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63378-7	Trunnion Link	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
65-63378-9	Trunnion Link	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63397-*	Lower Side Strut Assy.	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63397-9	Lower Side Strut Assy.	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63663-1	Bellcrank	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63663-*	Bellcrank	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63663-3	Bellcrank	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63663-9	Bellcrank	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63667-*	Bellcrank	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63667-15	Bellcrank	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63667-16	Link Assy.	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63667-23	Link Assy.	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63667-24	Link Assy.	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63667-5	Link Assy. Matched Set	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63667-7	Link Assy.	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-63667-8	Link Assy.	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-67963-*	Upper Torsion Link	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-67963-3	Upper Torsion Link	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
65-80051-1	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-80051-10	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-80051-11	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-80051-12	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-80051-*	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-80051-13	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-80051-14	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-80051-18	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-80051-2	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-80051-20	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-80051-3	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-80051-4	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-80051-5	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-80051-6	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-80051-7	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-80051-8	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
65-80051-9	Upper Drag Brace	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
65-82768-1	Beam Link Assy.	Overhaul	57-41-21	Boeing	737	AF	Yes	6/23/2010	RWJ
65-82768-*	Beam Link Assy.	Overhaul	57-41-21	Boeing	737	AF	Yes	6/23/2010	RWJ
65-82768-2	Beam Link Assy.	Overhaul	57-41-21	Boeing	737	AF	Yes	6/23/2010	RWJ
65-82768-4	FWD Link Assy. ((R/H))	Overhaul	57-41-21	Boeing	737	AF	Yes	6/23/2010	RWJ
65-82768-6	AFT Link Assy. ((R/H))	Overhaul	57-41-21	Boeing	737	AF	Yes	6/23/2010	RWJ
65-82768-7	Beam Link Assy (L/H)	Overhaul	57-41-21	Boeing	737	AF	Yes	6/23/2010	RWJ
65B01547-*	Bearing Housing	Repair	32-30-75	Boeing	747	LG	Yes	6/23/2010	RWJ
65B01547-2	Bearing Housing	Repair	32-30-75	Boeing	747	LG	Yes	6/23/2010	RWJ
65B01564	Head End	Repair	32-11-71	Boeing	747	LG	Yes	6/23/2010	RWJ
65B01564-*	Head End	Repair	32-11-71	Boeing	747	LG	Yes	6/23/2010	RWJ
65B01564-8	Head End	Repair	32-11-71	Boeing	747	LG	Yes	6/23/2010	RWJ
65B01564-9	Head End	Repair	32-11-71	Boeing	747	LG	Yes	6/23/2010	RWJ
65B05471-*	Pivot Pin	Overhaul	32-11-34	Boeing	747	LG	Yes	6/23/2010	RWJ
65B05471-4	Pivot Pin	Overhaul	32-11-34	Boeing	747	LG	Yes	6/23/2010	RWJ
65B81950-12	Support Assy	Repair	27-52-21	Boeing	747	AF	Yes	6/23/2010	RWJ
65B81950-*	Support Assy	Repair	27-52-21	Boeing	747	AF	Yes	6/23/2010	RWJ
65B81950-9	Support Assy.	Repair	27-52-21	Boeing	747	AF	Yes	6/23/2010	RWJ
65B81955-*	Upper Housing	Repair	27-52-11	Boeing	747	AF	Yes	6/23/2010	RWJ
65B81955-4	Upper Housing	Repair	27-52-11	Boeing	747	AF	Yes	6/23/2010	RWJ
65B81957-*	Housing	Repair	27-52-11	Boeing	747	AF	Yes	6/23/2010	RWJ
65B81957-8	Housing	Repair	27-52-11	Boeing	747	AF	Yes	6/23/2010	RWJ
65B81958-*	Support	Repair	27-52-42	Boeing	747	AF	Yes	6/23/2010	RWJ
65B81958-5	Support	Repair	27-52-42	Boeing	747	AF	Yes	6/23/2010	RWJ
65B81958-6	Support	Repair	27-52-42	Boeing	747	AF	Yes	6/23/2010	RWJ
65B81959-*	Support	Repair	27-52-42	Boeing	747	AF	Yes	6/23/2010	RWJ
65B81959-5	Support	Repair	27-52-42	Boeing	747	AF	Yes	6/23/2010	RWJ
65B81982-6	Support	Repair	27-52-11	Boeing	747	AF	Yes	6/23/2010	RWJ
65B81995*	Lower-Assy. Housing	Repair	27-52-21	Boeing	747	AF	Yes	6/23/2010	RWJ
65B81995-6	Lower-Assy. Housing	Repair	27-52-21	Boeing	747	AF	Yes	6/23/2010	RWJ
65B81995-8	Housing	Repair	27-52-21	Boeing	747	AF	Yes	6/23/2010	RWJ
65B82407-*	Housing	Repair	27-52-42	Boeing	747	AF	Yes	6/23/2010	RWJ
65B82407-2	Housing	Repair	27-52-42	Boeing	747	AF	Yes	6/23/2010	RWJ
65B82586-1	Piston	Repair	32-34-12	Boeing	747	LG	Yes	6/23/2010	RWJ
65B82586-*	Piston	Repair	32-34-12	Boeing	747	LG	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
65B82589-1	Head Assy.	Repair	32-34-12	Boeing	747	LG	Yes	6/23/2010	RWJ
65B82589-*	Head Assy.	Repair	32-34-12	Boeing	747	LG	Yes	6/23/2010	RWJ
65B90349-*	Universal Fitting Assy.	Overhaul	71-20-01	Boeing	747	Acc.	Yes	6/23/2010	RWJ
65B90349-4	Universal Fitting Assy.	Overhaul	71-20-01	Boeing	747	Acc.	Yes	6/23/2010	RWJ
65C27530-*	Quadrant	Repair	32-34-17	Boeing	737	LG	Yes	6/23/2010	RWJ
65C27530-4	Quadrant	Repair	32-34-17	Boeing	737	LG	Yes	6/23/2010	RWJ
65C31505-*	Shaft	Repair	27-16-11	Boeing	737	AF	Yes	6/23/2010	RWJ
65C31505-2	Shaft	Repair	27-16-11	Boeing	737	AF	Yes	6/23/2010	RWJ
65C33654-1	Spring Bracket	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65C33654-*	Spring Bracket	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65C33654-2	Spring Bracket	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65C33654-7	Spring Bracket	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65C33654-8	Spring Bracket	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
65C34776-1	(L/H) Trunnion Pin	Overhaul	32-21-38	Boeing	737	LG	Yes	6/23/2010	RWJ
65C34776-*	(L/H) Trunnion Pin	Overhaul	32-21-38	Boeing	737	LG	Yes	6/23/2010	RWJ
65C34809-*	Flap Track	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65C34809-2	Flap Track	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65C34810-1	Flap Track	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65C34810-*	Flap Track	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65C34812-*	Flap Track Assy.	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65C34812-2	Flap Track Assy.	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65C34812-6	Flap Track Assy.	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65C35162-1	Spacer	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65C35162-*	Spacer	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65C35163-3	Spacer	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65C35164-1	Spacer	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65C35164-*	Spacer	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65C35165-*	Flap Track	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65C35165-2	Flap Track	Overhaul	57-53-16	Boeing	737	AF	Yes	6/23/2010	RWJ
65C35276-*	Flap Track Assy.	Overhaul	57-53-15	Boeing	737	AF	Yes	6/23/2010	RWJ
65C35276-2	Flap Track Assy.	Overhaul	57-53-16	Boeing	737	AF	Yes	6/23/2010	RWJ
65C36351-10	Support Tube Lower Seg.	Overhaul	57-15-01	Boeing	737	AF	Yes	6/23/2010	RWJ
65C36351-*	Support Tube	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65C36351-14	Upper Segment	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
65C36351-5	Orifice Support Tube	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65C36351-6	Lower Segment	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
65C36459-*	Bolt	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
65C36459-2	Bolt	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
69-35394-*	Pin	Repair	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
69-35394-3	Pin	Repair	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
69-35394-4	Pin	Overhaul	32-01-03	Boeing	737	LG	Yes	6/23/2010	RWJ
69-35679-1	Retainer	Overhaul	27-09-09	Boeing	737	AF	Yes	6/23/2010	RWJ
69-35679-*	Retainer	Overhaul	27-09-09	Boeing	737	AF	Yes	6/23/2010	RWJ
69-38997-*	Spring Assy.	Overhaul	32-17-11	Boeing	737	LG	Yes	12/22/2015	RWJ
69-38997-7	Spring Assy.	Overhaul	32-17-11	Boeing	737	LG	Yes	12/22/2015	RWJ
69-38999-*	Shaft	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-38999-2	Shaft	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-38999-3	Support Shaft	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-38999-4	Spring Support Shaft	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39461-*	Shaft	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39461-2	Shaft	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39462-*	Link Assy. Stop	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39462-3	Link Assy. Stop	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39463-*	Bolt	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39463-2	Bolt	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39464-*	Bolt	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39464-4	Bolt	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39465-10	Gland Nut	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39465-*	Gland Nut	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39465-18	Glandnut	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39465-20	Glandnut	Overhaul	32-11-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39473-*	Bolt	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39473-3	Bolt	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39473-6	Bolt	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39474-1	Pin	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39474-*	Pin	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39475-1	Pin	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-39475-*	Pin	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
69-41248-*	Trunnion Pin (R/H)	Overhaul	32-21-38	Boeing	737	LG	Yes	6/23/2010	RWJ
69-41248-3	Trunnion Pin (R/H)	Overhaul	32-21-38	Boeing	737	LG	Yes	6/23/2010	RWJ
69-41624-1	Bolt	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-41624-*	Bolt	Overhaul	32-17-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-41633-1	Nut	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-41633-*	Nut	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-41633-3	Nut	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-41633-5	Nut	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-41634-1	Washer	Repair	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-41634-*	Washer	Repair	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-41634-4	Washer	Repair	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-51833-*	Bolt	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-51833-3	Bolt	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-51833-4	Bolt	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-51838-*	Retaining Collar	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-51838-3	Retaining Collar	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
69-53297-*	Shaft & Stud Assy.	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
69-53297-2	Shaft	Overhaul	32-34-13	Boeing	737	LG	Yes	6/23/2010	RWJ
69-54975-1	Stud Assy.	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
69-61785-*	O/S Bearing Assy.	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
69-61785-8M	O/S Bearing Assy.	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
69-61946-1	Stabilizer Tube	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
69-61946-*	Stabilizer Tube	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
69-62779-*	Bolt	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-62779-3	Bolt	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-62779-4	Bolt	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-68148-*	Bolt	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-68148-3	Bolt	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-68149-1	Bolt	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-68149-*	Bolt	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-68149-3	Bolt	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-68150-1	Bolt	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-68150-*	Bolt	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-68150-3	Bolt	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
69-68151-1	Bolt	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-68151-*	Bolt	Overhaul	32-17-11	Boeing	737	LG	Yes	6/23/2010	RWJ
69-68151-3	Bolt	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
69-72023-*	Pin	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-72023-4	Pin	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-72698-*	Pin	Overhaul	57-15-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-72698-4	Pin	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
69-72698-5	Pin	Overhaul	32-21-48	Boeing	737	LG	Yes	6/23/2010	RWJ
69-73169-1	Fusebolt	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-73169-*	Fusebolt	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-73169-3	Fusebolt	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-73176-*	Trunnion Bearing Bolt	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
69-73176-2	Trunnion Bearing Bolt	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
69-78313-1	Nut 1/16 U/S	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-78313-*	Nut	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
69-78313-2	Nut 1/8 U/S	Overhaul	32-16-01	Boeing	737	LG	Yes	6/23/2010	RWJ
810SW	Kit	Repair	78-11-23	Boeing	737	Acc.	Yes	6/23/2010	RWJ
811SW	Kit	Repair	78-11-23	Boeing	737	Acc.	Yes	6/23/2010	RWJ
93853-05	Hanger	Overhaul	71-20-21	Barry Contols	737	Acc.	Yes	6/23/2010	RWJ
93853-*	Hanger	Overhaul	71-20-21	Barry Contols	737	Acc.	Yes	6/23/2010	RWJ
BACB10BP12ACU	Nut	Repair	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
BACB30LJ20CD43	Bolt	Overhaul	32-16-31	Boeing	737	LG	Yes	6/23/2010	RWJ
BACN10BP12ACU	Nut	Repair	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
HFAB54-PL-109-*	Plate	Repair	Boeing Doc:PL313N3064	Boeing	757	SS	Yes	6/23/2010	RWJ
HFAB54-PL-109-3	Plate	Repair	Boeing Doc:PL313N3064	Boeing	757	SS	Yes	6/23/2010	RWJ
HFAB54-PL-109-4	Plate	Repair	Boeing Doc:PL313N3064	Boeing	757	SS	Yes	6/23/2010	RWJ
HFAB54-PL-109-5	Plate	Repair	Boeing Doc:PL313N3064	Boeing	757	SS	Yes	6/23/2010	RWJ
HFAB54-PL-109-6	Plate	Repair	Boeing Doc:PL313N3064	Boeing	757	SS	Yes	6/23/2010	RWJ
HFAB54-PL-109-7	Plate	Repair	Boeing Doc:PL313N3064	Boeing	757	SS	Yes	6/23/2010	RWJ
HFAB54-PL-109-8	Plate	Repair	Boeing Doc:PL313N3064	Boeing	757	SS	Yes	6/23/2010	RWJ
NAS1805-*	Nut	Repair	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
NAS1805-8P	Nut	Repair	71-21-37	Boeing	737	Acc.	Yes	6/23/2010	RWJ
161W1501-*	Fitting	Overhaul	32-11-82	Boeing	777	LG	Yes	6/29/2010	RWJ
161W1501-2	Fitting	Overhaul	32-11-82	Boeing	777	LG	Yes	6/29/2010	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
161T5010-1	Pin	Repair	32-11-36	Boeing	767	LG	Yes	7/8/2010	RWJ
161T5010-*	Pin	Repair	32-11-36	Boeing	767	LG	Yes	7/8/2010	RWJ
65-20744-*	Support Tube	Repair	32-22-04	Boeing	727	LG	Yes	7/14/2010	RWJ
AYG7173-1	Metering Pin	Repair	Specialized Services	MD	MD-11	SS	Yes	8/10/2010	RWJ
AYG7173-*	Metering Pin	Repair	Specialized Services	MD	MD-11	SS	Yes	8/10/2010	RWJ
AYG7178-*	Tube	Repair	Specialized Services	MD	MD-11	SS	Yes	8/10/2010	RWJ
AYG7178-503	Tube	Repair	Specialized Services	MD	MD-11	SS	Yes	8/10/2010	RWJ
47127-*	Pivot Pin	Repair	32-21-04	Bombardier	Q400	LG	Yes	8/25/2010	RWJ
47127-3	Pivot Pin	Repair	32-21-04	Bombardier	Q400	LG	Yes	8/25/2010	RWJ
161N1805-1	Pivot Pin	Overhaul	32-11-32	Boeing	757	LG	Yes	10/5/2010	RWJ
161N1805-*	Pivot Pin	Overhaul	32-11-32	Boeing	757	LG	Yes	10/5/2010	RWJ
ARG7060-*	Metering Pin	Repair	Specialized Services	MD	MD-11	SS	Yes	10/18/2010	RWJ
ARG7060-509	Metering Pin	Repair	Specialized Services	MD	MD-11	SS	Yes	10/18/2010	RWJ
AYG7442-*	Bearing Assy.	Repair	Specialized Services	MD	MD-11	SS	Yes	10/20/2010	RWJ
AYG7442-503	Bearing Assy.	Repair	Specialized Services	MD	MD-11	SS	Yes	10/20/2010	RWJ
315A1816-*	Piston	Repair	78-31-05 & 78-31-18	Boeing	737	Acc.	Yes	1/19/2011	MA
315A1816-2	Piston	Repair	78-31-05	Boeing	737	Acc.	Yes	1/19/2011	RWJ
315A1816-3	Piston	Repair	78-31-18	Boeing	737	Acc.	Yes	1/19/2011	RWJ
315A1842-*	Piston	Repair	78-31-04 & 78-31-19	Boeing	737	Acc.	Yes	1/19/2011	MA
315A1842-2	Piston	Repair	78-31-04	Boeing	737	Acc.	Yes	1/19/2011	RWJ
315A1842-4	Piston	Repair	78-31-19	Boeing	737	Acc.	Yes	1/19/2011	RWJ
315A2808-1	Cylinder	Repair	78-31-18	Boeing	737	Acc.	Yes	1/19/2011	RWJ
315A2808-*	Cylinder	Repair	78-31-18	Boeing	737	Acc.	Yes	1/19/2011	MA
65B10546-*	Door	Repair	Specialized Services	Boeing	747	SS	Yes	2/14/2011	RWJ
65B10546-32	Door	Repair	Specialized Services	Boeing	747	SS	Yes	2/14/2011	RWJ
201522255	MLG Bearing	Repair	Specialized Services	Airbus	A320	SS	Yes	2/18/2011	RWJ
311N3510-*	Ground Clip	Repair	Specialized Services	Boeing	757	SS	Yes	3/3/2011	RWJ
311N3510-181	Ground Clip	Repair	Specialized Services	Boeing	757	SS	Yes	3/3/2011	RWJ
314A1129-*	Seal	Repair	Specialized Services	Boeing	737	SS	Yes	3/15/2011	RWJ
314A1129-6	Seal	Repair	Specialized Services	Boeing	737	SS	Yes	3/15/2011	RWJ
314A1129-7	Seal	Repair	Specialized Services	Boeing	737	SS	Yes	3/15/2011	RWJ
5961560-1	Bearing	Repair	Specialized Services	Boeing	MD-80	SS	Yes	3/18/2011	RWJ
5961560-*	Bearing	Repair	Specialized Services	MD	MD-80	SS	Yes	3/18/2011	RWJ
69-35396-*	Bolt	Overhaul	32-01-03	Boeing	737	LG	Yes	3/21/2011	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
162N1142-12	Upper Support Plate	Repair	32-21-49	Boeing	757	LG	Yes	4/4/2011	RWJ
162N1142-*	Upper Support Plate	Repair	32-21-49	Boeing	757	LG	Yes	4/4/2011	RWJ
65C37821-*	Bushing	Repair	32-21-48	Boeing	737	LG	Yes	5/9/2011	RWJ
65C37821-2	Bushing	Repair	32-21-48	Boeing	737	LG	Yes	5/9/2011	RWJ
161N1833-*	Bushing	Repair	32-11-56	Boeing	757	LG	Yes	5/13/2011	RWJ
161N1833-2	Bushing	Repair	32-11-56	Boeing	757	LG	Yes	5/13/2011	RWJ
161N1823-1	Pin	Overhaul	32-11-32	Boeing	757	LG	Yes	8/4/2011	RWJ
161N1823-*	Pin	Overhaul	32-11-32	Boeing	757	LG	Yes	8/4/2011	RWJ
65C37819-*	#NULL!	Repair	32-21-48	Boeing	737	LG	Yes	8/23/2011	RWJ
65C37819-4	Bushing	Repair	32-21-48	Boeing	737	LG	Yes	8/23/2011	RWJ
65-27147-*	Outer Cylinder	Repair	DAP 104C-4702-13	Boeing	727	SS	Yes	10/13/2011	MA
65-27147-7	Outer Cylinder	Repair	DAP 104C-4702-13	Boeing	727	SS	Yes	10/13/2011	MA
65C37822-1	Apex Bolt	Overhaul	32-21-48	Boeing	737	LG	Yes	11/10/2011	RWJ
65C37822-*	Apex Bolt	Overhaul	32-21-48	Boeing	737	LG	Yes	11/10/2011	RWJ
162A1191-1	Metering Pin	Repair	32-21-49	Boeing	757	LG	Yes	11/23/2011	MA
162A1191-*	Metering Pin	Repair	32-21-49	Boeing	757	LG	Yes	11/23/2011	MA
162N1191-1	Metering Pin	Repair	32-21-49	Boeing	757	LG	Yes	11/23/2011	MA
162N1191-*	Metering Pin	Repair	32-21-49	Boeing	757	LG	Yes	11/23/2011	RWJ
65C37819-2	Bushing	Overhaul	32-21-48	Boeing	737	LG	Yes	12/5/2011	RWJ
MFAB32-BU-101-*	Bushing (65C37821-2)	Repair	Specialized Services	Boeing	737	SS	Yes	12/5/2011	RWJ
MFAB32-BU-101-75C	Bushing (65C37819-4)	Repair	Specialized Services	Boeing	737	SS	Yes	12/5/2011	RWJ
MFAB32-BU-101-80E	Bushing (65C37821-2)	Repair	Specialized Services	Boeing	737	SS	Yes	12/5/2011	RWJ
65C31332-*	Trunnion Bearing	Overhaul	32-16-31	Boeing	737	LG	Yes	1/3/2012	RWJ
65C31332-6	Trunnion Bearing	Overhaul	32-16-31	Boeing	737	LG	Yes	1/3/2012	RWJ
161T1156-*	Metering Pin	Repair	32-11-40	Boeing	737	LG	Yes	1/24/2012	RWJ
161T1156-4	Metering Pin	Repair	32-11-40	Boeing	737	LG	Yes	1/24/2012	RWJ
200811316	NLG Outer Cylinder	Repair	Specialized Services	Dowty	C-601	SS	Yes	1/27/2012	RWJ
65C37818-3	Bushing	Repair	Specialized Services	Boeing	737	SS	Yes	3/12/2012	RWJ
65C37818-4	Bushing	Repair	Specialized Services	Boeing	737	SS	Yes	3/12/2012	RWJ
65C37818-*	Bushing	Repair	Specialized Services	Boeing	737	SS	Yes	3/19/2012	RWJ
5912802-*	Tube	Repair	27-20-31	MD	MD-80	AF	Yes	4/10/2012	RWJ
5912802-7	Tube	Repair	27-20-31	MD	MD-80	AF	Yes	4/10/2012	RWJ
161N1803-*	Pin	Overhaul	32-11-32	Boeing	757	LG	Yes	5/17/2012	RWJ
161N1803-2	Pin	Overhaul	32-11-32	Boeing	757	LG	Yes	5/17/2012	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
697070317	Prop Hub	Repair	61-10-43	Dowty	C-130	Prop.	Yes	5/22/2012	RWJ
ACG7224-1	Metering Pin	Repair	Specialized Services	MD	MD-11	SS	Yes	6/6/2012	MA
ACG7224-*	Metering Pin	Repair	Specialized Services	MD	MD-11	SS	Yes	6/6/2012	MA
ARG7005-*	Chamber Tube	Repair	Specialized Services	MD	MD-11	SS	Yes	6/6/2012	MA
ARG7005-505	Chamber Tube	Repair	Specialized Services	MD	MD-11	SS	Yes	6/6/2012	MA
5-72334-3019	Torsion link	Repair	32-04-01	Boeing	707	LG	Yes	6/15/2012	RWJ
161N1841-*	Bushing	Repair	32-11-56	Boeing	757	LG	Yes	6/27/2012	RWJ
161N1841-2	Bushing	Repair	32-11-56	Boeing	757	LG	Yes	6/27/2012	RWJ
5951863-*	Beam	Repair	Specialized Services	MD	MD-80	SS	Yes	7/6/2012	RWJ
5951863-7	Beam	Repair	Specialized Services	MD	MD-80	SS	Yes	7/6/2012	RWJ
697070625	Prop hub	Repair	61-10-49	Dowty	MD-81	Prop.	Yes	7/10/2012	RWJ
ARG7060-505	Metering Pin	Repair	Specialized Services	MD	MD-82	SS	Yes	7/11/2012	RWJ
5951865-5	Adapter	Repair	Specialized Services	MD	MD-83	SS	Yes	7/18/2012	RWJ
65-46438-*	Track Assy	Overhaul	57-53-16	Boeing	MD-84	AF	Yes	7/18/2012	RWJ
65-46438-15	Track Assy	Overhaul	57-53-16	Boeing	MD-85	AF	Yes	7/18/2012	RWJ
161T7193-1-OSF125	Pivot Pin	Repair	32-11-36	Boeing	MD-86	LG	Yes	7/23/2012	RWJ
161T7193-1-OSF125-*	Pivot Pin	Repair	32-11-36	Boeing	MD-87	LG	Yes	7/23/2012	RWJ
162N1142-11	Upper Plate	Repair	32-21-49	Boeing	MD-88	LG	Yes	8/1/2012	RWJ
162N1187-*	Pin	Repair	32-21-49	Boeing	MD-89	LG	Yes	8/1/2012	RWJ
162N1187-3	Pin	Repair	32-21-49	Boeing	MD-90	LG	Yes	8/1/2012	RWJ
315A1105-*	Rub Strip	Repair	71-13-28	Boeing	MD-91	AF	Yes	8/30/2012	RWJ
315A1105-547	Rub Strip	Repair	71-13-28	Boeing	MD-92	AF	Yes	8/30/2012	RWJ
65C37814-5	Bearing Assy.	Overhaul	32-21-48	Boeing	MD-93	LG	Yes	9/19/2012	RWJ
SR09320112-3	Beam	Repair	32-17-00	MD	MD-95	LG	Yes	10/2/2012	RWJ
ACG7009-1	Metering Pin	Repair	32-21-01	MD	MD-96	SS	Yes	10/24/2012	RWJ
314N3216-4	Fitting	Repair	Boeing Blueprint	Boeing	MD-97	SS	Yes	10/30/2012	RWJ
5951861-1	Adapter	Repair	32-17-00	MD	MD-98	SS	Yes	11/21/2012	RWJ
161A1152-*	Orifice Support Tube	Repair	32-11-12	Boeing	MD-99	LG	Yes	11/27/2012	RWJ
161A1152-2	Orifice Support Tube	Repair	32-11-12	Boeing	MD-100	LG	Yes	11/27/2012	RWJ
65C34812-8	Flap Track Assy.	Overhaul	57-53-15	Boeing	MD-101	LG	Yes	12/3/2012	RWJ
161A1501-9	Outer Race	Overhaul	57-15-01	Boeing	MD-102	LG	Yes	12/4/2012	RWJ
65C34809-3	Track	Overhaul	57-53-15	Boeing	MD-103	AF	Yes	12/4/2012	RWJ
65C35163-*	Spacer	Overhaul	57-53-15	Boeing	MD-104	AF	Yes	12/4/2012	RWJ
65C35163-5	Spacer	Overhaul	57-53-15	Boeing	MD-105	AF	Yes	12/4/2012	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
65C31398-2	Steering Barrel	Overhaul	32-50-11	Boeing	MD-106	LG	Yes	1/30/2013	RWJ
697070600	Hub	Repair	61-10-49	Dowty	MD-107	SS	Yes	2/6/2013	RWJ
697039221	Cylinder	Repair	61-10-43	Dowty	MD-108	Prop.	Yes	5/10/2013	RWJ
697070230	Cylinder	Repair	61-10-49	Dowty	Dash 8	Prop.	Yes	5/31/2013	RWJ
161N1626-*	Axle Sleeve	Repair	32-11-56	Boeing	MD-109	LG	Yes	6/26/2013	MA
161N1626-4	Axle Sleeve	Repair	32-11-56	Boeing	MD-110	LG	Yes	6/26/2013	MA
162A1420-*	Steering Collar	Overhaul	32-21-12	Boeing	MD-111	LG	Yes	7/2/2013	RWJ
162A1420-2	Steering Collar	Overhaul	32-21-12	Boeing	MD-112	LG	Yes	7/2/2013	RWJ
660712302	Crosshead	Repair	61-10-39	Dowty	Saab 340	Prop.	Yes	7/11/2013	RWJ
660710377	Crosshead	Repair	61-10-39	Dowty	Saab 340	Prop.	Yes	7/11/2013	RWJ
660710369	Crosshead	Repair	61-10-39	Dowty	Saab 340	Prop.	Yes	8/8/2013	RWJ
OS65C37819-4	Bushing	Repair	32-21-48	Boeing	737	LG	Yes	11/1/2013	RWJ
OS65C37821-2	Bushing	Repair	32-21-48	Boeing	737	LG	Yes	11/1/2013	RWJ
MFAB32-BU-101-80	Bushing	Repair	32-21-48	Boeing	737	LG	Yes	11/18/2013	RWJ
MFAB32-BU-101-80-*	Bushing	Repair	32-21-48	Boeing	737	LG	Yes	11/18/2013	RWJ
MFAB32-BU-100-75	Bushing	Repair	32-21-48	Boeing	737	LG	Yes	11/18/2013	RWJ
MFAB32-BU-100-75-*	Bushing	Repair	32-21-48	Boeing	737	LG	Yes	11/18/2013	RWJ
311A1310U89	Rub Strip	Repair	N/A	Boeing	737	AF	Yes	11/26/2013	RWJ
660712675	Cylinder	Repair	61-10-39	Dowty	Saab 340	Prop.	Yes	12/16/2013	RWJ
161N1831-11	Bushing	Repair	32-11-56	Boeing	757	LG	Yes	12/16/2013	RWJ
1010562	Rub Strip	Repair	N/A	Boeing	737	SS	Yes	1/24/2014	RWJ
5-72334-3010	Upper Torsion Link	Repair	4A4-24-13	Boeing	707	LG	Yes	1/29/2014	RWJ
1010635	Rub Strip	Repair	20-10-05	Boeing	737	AF	Yes	2/28/2014	RWJ
295W1702-1	Trunnion	Repair	32-51-13	Boeing	777	LG	Yes	3/4/2014	RWJ
295W1702-*	Trunnion	Repair	32-51-13	Boeing	777	LG	Yes	3/4/2014	RWJ
161N1806-1	Pin	Repair	32-11-32	Boeing	757	LG	Yes	3/4/2014	RWJ
293W2310-1	Nut	Repair	32-21-05	Boeing	777	LG	Yes	4/22/2014	RWJ
65C27409-26	Carriage	Overhaul	57-53-36	Boeing	737	AF	Yes	4/30/2014	RWJ
65C27409-*	Carriage	Overhaul	57-53-36	Boeing	737	AF	Yes	4/30/2014	RWJ
5-72334-3013	Lower Torsion Link	Repair	32-04-01	Boeing	707	LG	Yes	5/6/2014	RWJ
162W1525-3	Lower Bearing Carrier	Repair	32-21-03	Boeing	777	LG	Yes	5/12/2014	RWJ
114A7522-5	Track	Overhaul	57-43-02	Boeing	737	AF	Yes	5/30/2014	RWJ
114A7521-5	Track	Overhaul	57-43-02	Boeing	737	AF	Yes	5/30/2014	RWJ
161W2168-4	Tow Fitting	Overhaul	32-11-37	Boeing	777	LG	Yes	6/2/2014	RWJ

Acc.: Accessory / LG: Landing Gear
AF: Airframe / Prop.: Propeller
SS - Specialized Services / (*): all dash numbers

Capabilities List

Aircraft Tooling Capabilities List

Revision 27
Revised Date: 7/28/2015

Part Number	Description	Capability	OHM/CMM	MFG	AC Type	Rating	Self Evaluation	Date	Accepted By
161W2168-*	Tow Fitting	Overhaul	32-11-37	Boeing	777	LG	Yes	6/2/2014	RWJ
1010957	Rub Strip	Repair	SOP 201005	Boeing	737	AF	Yes	6/20/2014	RWJ
660714289	Hub Assembly	Repair	61-10-36	Dowty	SF340	Prop.	Yes	10/14/2014	RWJ
660714255	Hub Assembly	Repair	61-10-36	Dowty	SF340	Prop.	Yes	10/14/2014	RWJ
275A1106-5	Rod End Assy.	Overhaul	32-51-52	Boeing	737	LG	Yes	2/16/2015	RWJ
275A1106-6	Rod End Assy.	Overhaul	32-51-52	Boeing	737	LG	Yes	2/16/2015	RWJ
275A1106-*	Rod End Assy.	Overhaul	32-51-52	Boeing	737	LG	Yes	2/16/2015	RWJ
65C36351-15	Pin	Overhaul	32-11-11	Boeing	737	LG	Yes	3/23/2015	RWJ
697039261	Crosshead Yoke	Repair	61-10-43-R	Dowty	C-130	Prop.	Yes	4/29/2015	RWJ